



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE



BRUCE KING  
GOVERNOR

ANITA LOCKWOOD  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

December 8, 1993

Ms. Susan Dolan  
Meridian Oil Incorporation  
P. O. Box 4289  
Farmington, NM 87499

Re: Southland Royalty Co.	East #1-M	N-26-31N-12W
Southland Royalty Co.	Thompson #2	C-28-31N-12W

Dear Susan:

As the enclosed copies of the 1993 Bradenhead Test reports indicate, the referenced wells were not tested because the Bradenheads were bullplugged. A review of past tests show the wells were tested in 1990. You are hereby directed to remove the bullplugs and test the wells prior to January 1, 1994.

Also, our records indicate the Thompson #2 has intermediate casing. The wellhead must be dug out to expose the Bradenhead spool, and the well tested properly.

Yours truly

Charles Gholson  
Deputy Oil & Gas Inspector

CG/ej

Enclosure

xc: well files