

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 3:01 pm, Jul 28, 2016

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact: Bruce Baker	
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982	
Facility Name: NEDU 503W	Facility Type: Injection Well	
Surface Owner State	Mineral Owner	API No. 30-025-06473

### LOCATION OF RELEASE

Unit Letter K	Section 10	Township 21S	Range 37E	Feet from the 2080'	North/South Line FSL	Feet from the 2080'	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	------------------------	-------------------------	------------------------	-----------------------	---------------

Latitude N32.4918556 Longitude W103.1526871

### NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 65 barrels of produced water	Volume Recovered: 60 barrels of produced water
Source of Release: Fiberglass Line	Date and Hour of Occurrence: 6/30/2016	Date and Hour of Discovery: 6/30/2016 at 7:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes (NMOCD)	
By Whom? Bruce Baker	Date and Hour 6/30/2016 at 4:09 p.m. via email.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The 2 inch fiberglass line came unglued tying in at main trunk line. The line was isolated and a vacuum truck was dispatched to pick-up standing fluid. The line has been repaired.		
Describe Area Affected and Cleanup Action Taken.* Majority of the release was contained at the junction box except for a small volume overfilled running down the lease road and impacted a small area of pasture on the ROW. The site has been mapped and samples collected.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

### OIL CONSERVATION DIVISION

Signature: <i>Bruce Baker</i>	Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Printed Name: Bruce Baker	Approval Date: 07/28/2016	Expiration Date: 09/28/2016
Title: Environmental Technician	Conditions of Approval:	
E-mail Address: larry.baker@apachecorp.com	Discrete samples only. Delineate and remediate per NMOCD guidelines.	
Date: 7/28/2016	Phone: (432) 631-6982	Attached <input type="checkbox"/> 1RP 4371 nJXK1621053945 pJXK1621054027

\* Attach Additional Sheets If Necessary