

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Wade Dittrich
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 390-2828
Facility Name	Iron Horse State #1 Battery	Facility Type	Battery

Surface Owner	State	Mineral Owner	State	API No.	30-025-38193
---------------	-------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	21	18S	35E	660	South	1830	East	Lea County, NM

Latitude N 32.21718° Longitude W 103.97635°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5 bbls oil & 15 bbls produced water	Volume Recovered	15 bbls
Source of Release	Leak is below load line on #1 oil tank	Date and Hour of Occurrence	08/06/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Olivia Yu- NMOCD, Amber Groves- SLO		
By Whom?	Wade Dittrich @ Oxy	Date and Hour	08/07/2017 @ 8:36 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 4:07 pm, Apr 17, 2018



Describe Cause of Problem and Remedial Action Taken.*

Spill was caused by a leak and is below the load line on #1 oil tank. The line has been repaired and is back in service.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 20' on location inside the lined containment. Remediation was completed by removing all of the contaminated material from within the lined facility and replacing it with clean material. The liner was inspected and the integrity of it is maintained.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Wade Dittrich	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 4/17/2018	Expiration Date: xx/xx/xxxx
E-mail Address: Wade_Dittrich@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-8-17 Phone: (575) 390-2828		

* Attach Additional Sheets If Necessary

1RP-4782