

From: [Yu, Olivia, EMNRD](#)
To: ["Alan Barksdale"](#); [Tara Hodges](#); [Ross Pearson](#); mnaranjo@slo.state.nm.us; ["Mann, Ryan"](#)
Cc: ballen@sesi-nm.com; books@sesi-nm.com
Subject: RE: Sunray State Tank Battery Closure Report 1RP-3619
Date: Wednesday, September 5, 2018 4:03:00 PM

Mr. Barksdale:

Please be advised that review of submitted reports would be greatly facilitated by clear documentation and presentation of data. In review of the closure report for 1RP-3619, please address the following concerns:

1. Where were the confirmation samples taken? Figure 2 does not have the locations of bottom and sidewall samples from November 2017 (SP-1 to SP-6) marked.
2. On Figure 2, when was the samples represented by Sample Point 1, 2, & 3 taken? Are these bottom or sidewall samples? Is there laboratory data?
3. Were BH-1 and BH-2 samples, collected on June 25, 2018, from the same original locations in June 2016? Was the impacted 3-4 ft. of soil removed and backfilled? In which case, the data presented in June 2018 are confirming that backfill material is clean?
4. What does BH-3A denote on Figure 2? There are no associated laboratory data for BH-3A.
5. Based on the scale of the release and the estimated depth to groundwater < 100 ft. bgs, if a 1 or 4 ft. excavation was conducted over the release area, confirmation sidewall and bottom samples, at no greater than 50 ft. apart, are required. Neither Figure 2 nor the text state to what depth the release area was excavated? Which area had 1 ft. or 4 ft. of impacted soil removed?

Moreover, the original concerns from the email dated March 30, 2018 have not been addressed. Is the area that is lined, denoted by a purple polygon? Is this the lined 12 x 12 ft. area? What depth is this excavation area?

Please address these issues point by point and submit a modified figure and tabulated data.

Thanks,
Olivia

From: Alan Barksdale <alan@redmountainresources.com>
Sent: Tuesday, August 7, 2018 12:01 PM
To: Tara Hodges <office2@sesi-nm.com>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Ross Pearson <ross@redmountainresources.com>; mnaranjo@slo.state.nm.us
Cc: ballen@sesi-nm.com; books@sesi-nm.com
Subject: RE: Sunray State Tank Battery Closure Report 1RP-3619

Ms. Yu:

Is there an update on the Sunray Closure Report?

Thanks,

Alan W. Barksdale
Red Mountain Resources, Inc.
14282 Gillis Rd
Farmers Branch, TX 75244
Office: +1 214.871.0400
Fax: +1 214.871.0406
Mobile: +1 501.412.4097
alan@redmountainresources.com

From: Tara Hodges [<mailto:office2@sesi-nm.com>]
Sent: Thursday, July 19, 2018 10:05 AM
To: olivia.yu@state.nm.us; Alan Barksdale; Ross Pearson; mnaranjo@slo.state.nm.us
Cc: ballen@sesi-nm.com; books@sesi-nm.com
Subject: Sunray State Tank Battery Closure Report 1RP-3619

Hello all!

I have attached, per Bob Allen SESI, the revised closure report for the Sunray State Tank Battery 1RP-3619. Please let us know if you have any questions.

Thank You

Tara Hodges

Safety & Environmental Solutions, Inc.
703 East Clinton Street
Hobbs, NM 88240
Office: (575) 397-0510