

From: [Hernandez, Christina, EMNRD](#)
To: ["Mann, Ryan"; "Jay Loudermilk"](#)
Cc: [Zane Kurtz](#)
Subject: RE: [EXT] RE: 1RP-5227 Centennial Godfather 36 State Com 1H Assessment
Date: Tuesday, November 13, 2018 1:24:00 PM
Attachments: [WorkPlan1RP-5227 Godfather 36 - Site Assessment Report FINAL \(002\).pdf](#)

Dear Mr. Loudermilk:

Notes:

- In the future, please be advised that initial C-141 form for a release must provide volume spill calculations/measurements such as: dimensions (L X W X depth of impact), soil parameters (porosity, texture, bulk density, soil moisture), meter readings, waste manifests, etc. This was initially requested by OCD on an email on 10/12/2018.
- Delineation/characterization of a spill must be done for all constituents of Table I of 19.15.29.11 NMAC, which includes: Chloride, TPH, BTEX, and Benzene.

The delineation/characterization submitted for **1RP-5227** is incomplete, however, in the interests of resolution NMOCD approves the proposed remediation plan with the following conditions:

1. Provide bottom and sidewall confirmation lab analyses for the excavation area at TP3-0', to include Benzene, BTEX and TPH extended analyses.
2. Submit laboratory analyses for all delineation sample locations at surface for Benzene, BTEX and TPH extended analyses.
3. Please include an additional delineation sample (all constituents) location at southern portion of spill (marked X on the delineation sample map) to complete horizontal delineation.
4. Dated photo documentation of the remedial activities.
5. Scaled map with the confirmation sample locations in relation to the delineation sample points.

Thanks,
Christina Hernandez
EMNRD-OCD
Environmental Specialist
1625 N. French Drive
Hobbs, NM 88240
575-393-6161 x111
Christina.Hernandez@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Mann, Ryan <rmann@slo.state.nm.us>
Sent: Monday, October 29, 2018 9:36 AM
To: 'Jay Loudermilk' <JLoudermilk@ntglobal.com>; Hernandez, Christina, EMNRD <Christina.Hernandez@state.nm.us>
Cc: Zane Kurtz <Zane.Kurtz@cdevinc.com>
Subject: [EXT] RE: 1RP-5227 Centennial Godfather 36 State Com 1H Assessment

NMSLO will with the following condition: For the off pad portion, if any topsoil was removed as part of the initial response then the same amount should be replaced. This area should also be seeded at the appropriate time. Let me know if you have any questions. Like approval is also necessary from NMOCD.

Ryan Mann
Remediation Specialist
Field Operation Division
(575) 392-3697
(505) 699-1989
New Mexico State Land Office
2827 N. Dal Paso Suite 117
Hobbs, NM 88240

From: Jay Loudermilk [<mailto:JLoudermilk@ntglobal.com>]
Sent: Thursday, October 25, 2018 10:59 AM
To: christina.hernandez@state.nm.us; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Zane Kurtz <Zane.Kurtz@cdevinc.com>
Subject: 1RP-5227 Centennial Godfather 36 State Com 1H Assessment
Importance: High

Ms. Hernandez & Mr. Mann,

Please see attached Site Assessment Report for the Centennial Godfather 36 State Com 1H Release.

Incident ID: nCH1828530607
District RP: 1RP-5227
Application ID: pCH1828531065

If you have any question regarding the report please do not hesitate to contact me.

Thanks,

Jay Loudermilk

Staff Scientist | **NTG Environmental**

701 Tradewinds Blvd, Suite C | Midland, Texas 79706

T: 432.848.4208 | M: 432.312.8049 | jloudermilk@ntglobal.com | ntglobal.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit https://clicktime.symantec.com/a/1/pSposjcCy-XxYaZpGYXMx3d2d2qdvscG-uNGh5Y4B0=?d=Mex1Yyf8JLoDxTr-13ixz5E8hFRURfFmyqMOSOCx94xTekeloqhtsU9kSLMMAowEk2k0d2JfHm_cDknXWmdtVtcBqyvSpog2o9Sz-4ehtGTy40dEgawB814e3aqxXBDJeNbBp0qRxQ86aCoDuybOFVDFIDf-A19OniQWzmq9kha6t_ZObbF9gutijVJFqDshMVLn703LylsuBgFHVkRbExVbIDjBbU-wsOrq0gQ2NYjSQRwo8spVsSarM7tEI0HiwrxFWxPzISOa_vRgQGoc6NEvHanbl_z7Hgdzbp1BqlGWWCko4gAzFSXY85yPo1q1O8M4m_4S00sWrqyTQDVkr4U0c7GNM4T6_Hs-v2S3HAP8R1puR2fpHABijpQ6yRP-_PdNaPxYtSjzIQD_6mTfa09YUT9Cxl%3D&u=http%3A%2F%2Fwww.symanteccloud.com