Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103		
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.		
District II	OIL CONSERVATION DIVISION		30-025-21644		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			✓ FEE □	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Suitu 1 0,	1111 07		6. State Oil &	Gas Lease No.
87505 SUNDRY NOTE	CES AND REPORTS ON	WELLS		7 Lease Name o	or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name: State 32	
1. Type of Well:					
Oil Well Gas Well Other SWD 2. Name of Operator				8. Well No.	
Bruce A. Wilbanks Company				2	
3. Address of Operator			9. Pool name or Wildcat		
P.O. Box 763, Midland, Te	exas 79702	· · · · · · · · · · · · · · · · · · ·		State Line F	Ellenburger
4. Well Location					
Unit Letter J :1980_feet from the South line and 1980feet from the East line					
Section 32	Township	23S	Range 38E	NMPM	I Lea County
	10. Lievation (blow wi		R, RKB, RT, GR, etc.		
3,313' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
		icate Na			
NOTICE OF IN PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	SEQUENT RE	:PORTOF: ALTERING CASING □
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	_	PLUG AND
					ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗆	
OTHER:			OTHER:		
OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion of recompilation.					
03/17/04 Notified OCD, Gary Wink. MIRU Triple N rig #23 and plugging equipment. OCD Buddy Hill on location.					
03/18/04 RIH w/ production tubing. PU workstring and tagged PBTD @ 9,485'. Circulated hole w/ mud. PHH w/ tsg and pumped 25 sx C cmt 6,600 – 6,350'. POOH w/ tbg					
03/19/04 OCD Buddy Hill on location. Cut and pulled 5½" casing from 3,497'. RIH w/ tbg to 3,547					
03/22/04 Notified OCD, Buddy Hill (on 3/12/04). Pumped 75 sx C cmt w/ 2% CaCl₂ @ 3,547'. WOC and tagged cmt @ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5					
•		·	•		nti ei
03/23/04 Tagged cmt @ 505'. Pumped 25 sx C cmt @ 505' per Buddy Hill. Circulated 25 sx C cmt 62' to surface. RDMO.					
03/29/04 Cut off wellhead & anchors, capped well & installed marker. Backfilled cellar.					
I hereby certify that the information	aboye is true and complete	to the be	st of my knowledge	and belief.	
SIGNATURE TO THE SIGNATURE	T	ITLE	Engineer		DATE <u>04/06/04</u>
Type or print name James F. Newman, P.E. Triple N Services, Inc. Telephone No. 432-637-1994					
(This space for State use)	Λ.		• • •		
APPPROVED BY Conditions of approval, if any:	or drill. Cu	XC F IELD) REPRESENTATIVI	E 11/STAFF MAN	APR 1 5 2004