Form 3160-5 (June 1990)

UNITED STATES N.M. OII Cons. Division DEPARTMENT OF THE INTERIOR S.S. N. French Dr. BUREAU OF LAND MANAGEMEN HODDS, NM 88240 JNDRY NOTICES AND DEPARTMENT.

FORM APPROVED Budget Bureau No. 1004-0135

	1 100001	Expires March 31, 1993
	S AND REPORTS ON WELLS	5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE 1. Type of Well Oil Gas Well Other Other DEVON ENERGY PRODUCTION COMPANY, LP.		NM-LC062391
		6. If Indian, Allottee or Tribe Name
		NA STATE OF THE ST
		7. If Unit or CA, Agreement Designation
		NA
		8. Well Name and No.
3. Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 228-7512		Kachina 5 Federal #1
		9. API Well No.
20 HONTH DRUMUWAT, SUITE 1500, O	NLAHUMA (111, UKLAHUMA 73102 (405) 228-7512	30-025-31113
4. Location of Well (Footage. Sec., T., R., M., or Survey Description) 330' FSL & 1980' FEL, SW SE Section 5-T18S-R33E		10. Field and Pool, or Exploratory Area
		South Corbin (Wolfcamp)
		11. County or Parish, State
		Lea County, New Mexico
CUECK ADDDODDIATE DOM) TO INDICATE MATERIAL	
) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	
	Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	New Construction Non-Routine Fracturing
_	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
3. Displace hole w/ 9.0# mud. 4. Set 170' cement plug from 8,100' to 8 5. Set 150' cement plug from 5,425' to 5 6. Shoot squeeze holes at 3,150' and circ 7. Set 150' cement plug inside 5-1/2" cas 8. Set 100' cement plug from 1,475' to 1 9. Shoot squeeze holes at 390' and circul 10. Set 150' cement plug inside 5-1/2" cas 11. Shoot squeeze holes at 60' and circul 12. Set surface cement plug in 5-1/2" cas 13. Cut off casings 3' below ground level. 14. Install dry hole marker. 15. Restore location Notify Carls	culate 100' cement in 5-1/2" annulus. sing from 3000' to 3150'. WOC and tag. ,575'. late 100' cement in 5-1/2" annulus. sing from 240' to 390'. WOC and tag. tte cement to surface in 5-1/2" annulus. Ing from 0' to 60'.	E ATTACHED FOR FIONS OF APPROVAL
Note: Cement class "C" at 14.8 ppg with a yield 14. I hereby certify that the foregoing is true and correct	1 of 1.32 cu. ft/sx	
Page 1 11	Ronnie Slack	1892: -1889
Signed Name Stack	Title Operations Technician	Date 5/13/04
This space for Federal of State office use)		
Approved by (ORIG. SGD.) DAVID R. GL. Conditions of approval, iMAY 1 7 2004	ASS Title	Date
Fitle 18 U.S.C. Section p.00 to makes it a crime for any person know o any matter within its jurisdiction.	ngly and willfully to make to any department or agency of the United States an	y false, fictitious or fraudulent statements or representation



