

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-33007
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-2731
7. Lease Name or Unit Agreement Name J.F.G. State
8. Well No. #1
9. Pool name or Wildcat Epst EK

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Morexco, Inc.	
3. Address of Operator 1591 Roswell 88202-1591 P.O. Box 481, Artesia, N.M. 88210	
4. Well Location Unit Letter J : 1650 Feet From The South Line and 2310 Feet From The East Line Section 15 Township 18S Range 34E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) 12-23 NNOCD-Billy P. & Chriss W.
- 2) 12-28 Set CIBP @ 4394'
- 3) Dumpbail 5 sx at 4394 to 4344'
- 4) Circ. 5-1/2" csg w/ .9.5 #/gal gelled mud.
- 5) 12-19 Spot 25 sx @ 2650 to 2404'
- 6) Cut and pull 5-1/2 csg from 1676.
- 7) Mix and spot 30 sx @ 1726'
- 8) 12-20 RIH w/tbg to tag TOC @ 1583'.
- 9) Spot 30 sx @ 1265, WOC & Tag TOC @ 1154'.
- 10) Spot 10 sx 30' to Surf.
- 11) Cut WH & Deadmen, install dry hole marker and backfill pit and cellar. ASAP.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Area Manager DATE 12-30-99  
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 570-0646

(This space for State Use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JUL 16 2004  
CONDITIONS OF APPROVAL IF ANY: