Office	State of New Mexico	
District I	Energy, Minerals and Natural Reso	ources June 19, 2008 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		00 005 00000
1301 W. Grand Avc., Artesia, NM 882 10	ONSERVATION DIVIS	5 Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	TEXT South St. Planeis Dr.	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM NOV 1	3 2011 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		A-2614
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSECS DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	TOHIBILL OR TO DEEPEN OR PLUG BACK IN FOR PERMIT" (FORM C-101) FOR SUCH	Webonald State A/O 1
1. Type of Well: ⊠Oil Well ☐ Gas	Well 🗖 Other: 🖊	8. Well Number ₀₁₀
Name of Operator Apache Corporation		9. OGRID Number 873
3. Address of Operator	** II	10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 M	/ildiand, IX 79705	South Eunice - 7Rvrs/Queen
4. Well Location	foot from the Courts lie	ne and 1980 feet from the West
Unit Letter K : 1980 Section 16	feet from the South lin Township 22S Range 366	
	Elevation (Show whether DR, RKB, R	
	58' GL	7, On, all.)
12. Check Appr	opriate Box to Indicate Nature o	f Notice, Report or Other Data
NOTICE OF INTEN	ITION TO:	SUBSEQUENT REPORT OF:
	· · · · · · · · · · · · · · · · · · ·	DIAL WORK ALTERING CASING
		IENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING ML	ILTIPLE COMPL CASIN	G/CEMENT JOB
DOWNHOLE COMMINGLE		
OTHER:	П	Repair Bradenhead Leak
		details, and give pertinent dates, including estimated date
		letions: Attach wellbore diagram of proposed completion
or recompletion.		
•	bradenhead. Apache performed the fo	llowing to correct the problem:
This well started leaking water out the	. ,	llowing to correct the problem:
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub processing the control of t	ump & tbg.	llowing to correct the problem:
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub pt 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' w	ump & tbg. d. Log from 3540'-Surface. v/2 SPF, 4 holes.	llowing to correct the problem:
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub print 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' viluses 10/29/2011 Open csg to frac tanks. Viluses in the started started started in the started	ump & tbg. d. Log from 3540'-Surface. d/2 SPF, 4 holes. VO wire line.	
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub pt 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' v 10/29/2011 Open csg to frac tanks. V 11/01/2011 RIH w/cmt retainer to 248	ump & tbg. ad. Log from 3540'-Surface. ad/2 SPF, 4 holes. VO wire line. 5'; pump 500 sx cement. 11/02/2011	Test cement retainer.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/O wire line. b/C wire soon sx cement. 11/02/2011 b/C csg parted. 11/04/2011 Repaired b/C control clean. PU above squeeze ho	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 St	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/0 wire line. b'; pump 500 sx cement. 11/02/2011 b'; csg parted. 11/04/2011 Repaired bego; circ clean. PU above squeeze ho	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/0 wire line. b'; pump 500 sx cement. 11/02/2011 95'; csg parted. 11/04/2011 Repaired 609'; circ clean. PU above squeeze ho abools.	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Starting 11/10/2011 POOH, release RBP, LD 11/10/2011 P	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/0 wire line. b'; pump 500 sx cement. 11/02/2011 95'; csg parted. 11/04/2011 Repaired 609'; circ clean. PU above squeeze ho abools.	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Starting 11/10/2011 POOH, release RBP, LD 11/10/2011 P	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/0 wire line. b'; pump 500 sx cement. 11/02/2011 b'; csg parted. 11/04/2011 Repaired b(09'; circ clean. PU above squeeze howab b(000)s. b(000)s. b(000)s. b(000)s.	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub production 10/27/2011 RIH w/B&S test csg - good 10/28/2011 RIH w/slick gun to 2550' volume 10/29/2011 Open csg to frac tanks. Volume 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Starting 11/10/2011 POOH, release RBP, LD 11/10/2011 P	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/2 SPF, 4 holes. a/2 SPF, 4 holes. b/2 Wire line. b/3; pump 500 sx cement. 11/02/2011 b/4; csg parted. 11/04/2011 Repaired b/4609'; circ clean. PU above squeeze howab b/4600s. b/4600scools. b/4600	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub print 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' viv. 10/29/2011 Open csg to frac tanks. Viv. 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Still 11/10/2011 POOH, release RBP, LD 11/11/2011 RIH w/prod equip; land put	ump & tbg. ad. Log from 3540'-Surface. a/2 SPF, 4 holes. a/0 wire line. b'; pump 500 sx cement. 11/02/2011 b'; csg parted. 11/04/2011 Repaired b(09'; circ clean. PU above squeeze howab b(000)s. b(000)s. b(000)s. b(000)s.	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub pi 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' v 10/29/2011 Open csg to frac tanks. V 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 St 11/10/2011 POOH, release RBP, LD of 11/11/2011 RIH w/prod equip; land pu	ump & tbg. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. by SPF, 4 holes. by Owire line. 5'; pump 500 sx cement. 11/02/2011 95'; csg parted. 11/04/2011 Repaired 609'; circ clean. PU above squeeze howab cools. amp @ 3350'. RTP Rig Release Date:	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub print 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' viv. 10/29/2011 Open csg to frac tanks. Viv. 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Still 11/10/2011 POOH, release RBP, LD 11/11/2011 RIH w/prod equip; land put	ump & tbg. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. by SPF, 4 holes. by Owire line. 5'; pump 500 sx cement. 11/02/2011 95'; csg parted. 11/04/2011 Repaired 609'; circ clean. PU above squeeze howab cools. amp @ 3350'. RTP Rig Release Date:	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub pi 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' v 10/29/2011 Open csg to frac tanks. V 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/03/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 St 11/10/2011 POOH, release RBP, LD of 11/11/2011 RIH w/prod equip; land pu Spud Date: 03/22/1938	ump & tbg. ad. Log from 3540'-Surface. ad/2 SPF, 4 holes. ad/2 SPF, 4 holes. ad/2 SPF, 4 holes. by O wire line. by Course line	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub pi 10/27/2011 RIH w/B&S test csg - goo 10/28/2011 RIH w/slick gun to 2550' v 10/29/2011 Open csg to frac tanks. V 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 St 11/10/2011 POOH, release RBP, LD of 11/11/2011 RIH w/prod equip; land pu	ump & tbg. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. ad. Log from 3540'-Surface. by SPF, 4 holes. by Owire line. 5'; pump 500 sx cement. 11/02/2011 95'; csg parted. 11/04/2011 Repaired 609'; circ clean. PU above squeeze howab cools. amp @ 3350'. RTP Rig Release Date:	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'.
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub principal princi	with the standard sta	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'. //01/1938 knowledge and belief. DATE 11/16/2011
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub print 10/27/2011 RIH w/B&S test csg - god 10/28/2011 RIH w/slick gun to 2550' vive 10/29/2011 Open csg to frac tanks. Vive 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Still/10/2011 POOH, release RBP, LD 11/11/2011 RIH w/prod equip; land put 11/11	ump & tbg. ad. Log from 3540'-Surface. ad/2 SPF, 4 holes. ad/2 SPF, 4 holes. ad/2 SPF, 4 holes. by O wire line. by Course line	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'. //01/1938 knowledge and belief. DATE 11/16/2011
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub prints of the process of t	with the control of t	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'. 7/01/1938 Fech DATE 11/16/2011 Holland@apachecorp.com PHONE: 432/818-1062
This well started leaking water out the 10/26/2011 MIRUSU POOH w/sub print 10/27/2011 RIH w/B&S test csg - god 10/28/2011 RIH w/slick gun to 2550' vive 10/29/2011 Open csg to frac tanks. Vive 11/01/2011 RIH w/cmt retainer to 248 11/03/2011 DO cmt ret, tag cmt @ 24 11/07/2011 DO cmt ret & cement to 2 11/08/2011 Run CBL 11/09/2011 Still/10/2011 POOH, release RBP, LD 11/11/2011 RIH w/prod equip; land put 11/11	with the standard sta	Test cement retainer. csg. 11/05/2011 Pump 500 sx cmt. les @ 2550'. //01/1938 rknowledge and belief. Tech DATE 11/16/2011 Holland@apachecorp.com PHONE: 432/818-1062