

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-08194
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>Injection</u>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator OXY USA Inc.		6. State Oil & Gas Lease No. E-5009
3. Address of Operator P.O. Box 50250 Midland, TX 79710		7. Lease Name or Unit Agreement Name Cotton Draw Unit
4. Well Location Unit Letter <u>H</u> : <u>1980</u> feet from the <u>north</u> line and <u>660</u> feet from the <u>east</u> line Section <u>16</u> Township <u>25S</u> Range <u>32E</u> NMPM County <u>Lea</u>		8. Well Number <u>3</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3435'</u>		9. OGRID Number 16696
		10. Pool name or Wildcat Paduca Delaware

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: CIBP, MIT-TA Status ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This Approval of Temporary
Abandonment Expires 7-13-2016

6/26/12 MIRU PU
6/27/12 Well dead, test csg to 500# for 20 minutes, Held OK. NDWH, NU BOP, Rel pkr, POOH with 4-1/2" pkr, RIH with tapered mill to 3000'.
6/28/12 Continue in the w/ mill to 4600', POOH. RIH w/ CIBP & set @ 4582', dump bail 35' cmt on top of CIBP. Circ hole w/ pkr fluid, test csg to 500#, Held OK. LD tbq.
6/29/12 ND BOP, NUWH, well TA'd, will set up a mechanical integrity test Monday. RDPU
7/13/12 Run TA MIT, test to 510# for 30 minutes, witnessed by Mark Whitaker-NMOCD.

Spud Date:

Rig Release Date:


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Advisor DATE 7/23/11

Type or print name David Stewart E-mail address: david_stewart@oxy.com PHONE: 432-685-5717
For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr. DATE 7-30-2012
Conditions of Approval (if any):

JUL 26 2012



Tested
7-13-2012

Bumped
Recorder
MW

Find ppi

Find ppi

Handwritten signature
OGD

HOBBS OGD


JUL 25 2012

RECEIVED

OXY-USA INC
Cotton Draw Unit #3
30-025-08194
UL-H, SEC 16, T2SS, R32E
T/A Status Test

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

OXY USA Inc. - Current
Cotton Draw Unit #3
API No. 30-025-08194



12-1/4" hole @ 367'
8-5/8" csg @ 367'
w/ 263sx-TOC-Surf-Circ

1985-Sqz csg lk @ 308-704' w/ 1210sx-Circ-Surf

6-3/4" hole @ 4778'
4-1/2" csg @ 4778'
w/ 150sx-TOC-3583'-Calc

CIBP @ 4582' w/ 35' cmt

Perfs @ 4663-4700'

TD-4778'