Office	Sta	ate of Ne	w Mexico			Form C-103			
DISTRICT I 1625 N. French Dr., Hobbs NM 88240	Energy, Minerals and Natural Resources				VA/CLL A	Revised March 25, 1999			
DISTRICT II 1301 W. Grand Avenue, Artesia NM 88210	OIL CONSERVATION DIVISION				VVELLA	WELL API NO.			
DISTRICT III	1220 South St. Francis Dr.				5 Indica	30-025-33574 5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec NM 87410	Santa Fe, New Mexico 87504-2088					STATE X FEE			
DISTRICT IV 1220 S. St. Francis Dr., Santa Fe, NM 87505					6. State	6. State Oil & Gas Lease No.			
					7 1 0000	V-4297 7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					/ Lease	Name of Of	iit Agreemei	it ivame	
1. Type of Well:					C	Coriander AOC State			
Oil Well X Gas Well Other									
					8. Well N	1 0.			
Yates Petroleum Corporation 3. Address of Operator						2			
3. Address of Operator						9. Pool Name or Wildcat			
105 South 4th Str., Artesia, NM 88210						Red Tank Delaware, West Red Tank Bone Springs			
4. Well Location					l				
Unit Letter H 1650	_ feet from theNo	orth	_ line and	330	feet fron	n the	East lir	ne l	
Section 1	Township 23S R	Range	32E NM	PM		County	Lea	ı	
10. E	levation (Show whether D 3731' GR	PF, RKB, F	RT, GR, etc.)		i i		100		
11. Check Appropriate Box		Notice.	Report, or Of	her Data		2980			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WORK	PLUG AND ABANDON	ล	REMEDIAL WORK		ALTERING				
TEMPORARILY ABANDON	CHANGE PLANS	-	COMMENCE DRIL	LING OPNS		ABANDONMENT			
PULL OR ALTER CASING	MULTIPLE	=	CASING TEST AN	L		, ADA ADOMNER			
OTHER:	COMPLETION	-							
			OTHER:						
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.									
Propose to plug and al	bandon as follows	:				(35 W	\$17 15 18 2.	0 _{27.}	
1) Dump 35' cement on CIBP @ 7000'. 2) Spot 100' cement plug 4840-4740'. WOC and tag.									
2) Spot 100' cement plug 4840-4740'. WOC and tog									
2) Spot 100' cement plug 4840-4740'. WOC and tag.									
Terrorate @ 1200. Place of sx plug 1205-1103, inside and outside casing. WOC and tag. Hobbs									
✓4) Spot 10 sx plug @ surface.									
5) Cut off wellhead, weld on plate, and install dry-hole marker.									
JSPOT 100' CEM	MENTPLUG E	- 400'-	= 300 (F)	RESH WATE	ER PLU	b)	CI- It	er Fr	
, , , , , ,		•	HOURS PRIC	ission must b OR TO THE BI	BE NOTIFIE EGINNING	D 24			
			PLUGGING	OPERATIONS F	OR THE C	-103			
			TO BE APPR						
Thereby certify that the information	n above a true and comple	te to the b	est of my know	edge and belief.					
SIGNATURE	Dans	TITLE	Regulatory	Compliance Tec	hnician	_ DATE	6/16/0)3	
	ni Davis				т	elephone No.	505-748-	1471	
APPROVED BY LOUIS LINE OF FIELD REPRESENTATIVE II/STAFF MANAGER									
APPROVED BY Conditions of approval, if any:	Jw. wink	TILE	THE NET REC	LATATIVE 11/3	IMIT MAN	TOATE _#	IN 1 0	2002	
Conditions of approval, it arry.	\mathcal{U}					J.	JI 1 3 /	たいいろ	