Office Office	State of New Mexico			Form C-103		
District I	Energy, Minerals a	nd Natura	l Resources	WELL ADINO	Octob	er 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-40615	-	_
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type	of Lease	1
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	☐ FEE S	a
District IV	Santa Fe, NM 8/505				as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTI	CES AND REPORTS ON	WELLS		7. Lease Name of	or Unit Agreemen	nt Name
(DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLIC	SALS TO DRILL OR TO DEEPE	EN OR PLACE	DOCO TO A			i
PROPOSALS.)	JATION FOR PERMIT" (FORM			J R Phillips (30	<i>4333)</i>	
	Gas Well	250	5 2014	8. Well Number	12	
2. Name of Operator		DEC .		9. OGRID Num	ber 873	121 11 11
Apache Corp.			CASA DECE	10 P 1	337'11 .	
3. Address of OperatorP O box Drawer D Monument NM	99765	REC	CENTED	10. Pool name o Paddock	r Wildcat	
				raudock		
4. Well Location		N .	1. 1	0040	6 . 61	
	:570feet from the	N_	line and	2240	feet from the	
Eline		30G F	265)		
Section 1	Township 2 11. Elevation (Show whe		lange 36E	NMPM	Lea Cou	inty
	II. Elevation (Snow wne	einer DK, K	KB, KI, GK, etc.,			
	<u>8 </u>					## 54°W46 5-,35#6,949
12 Check A	Appropriate Box to Ind	licate Nat	ure of Notice	Report or Other	r Data	
12. CHECK F	appropriate box to file	iicaic ivai	uic of Notice,	Report of Other	Data	
NOTICE OF INTENTION TO: SUB				SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					ALTERING CA	SING 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	LLING OPNS.□	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN	Т ЈОВ 🔲		
DOWNHOLE COMMINGLE						
OTUED.	r	_	OTUED.		_	,
OTHER: 13. Describe proposed or comp	leted operations (Clearly)		OTHER: rtinent details, an	d give pertinent da	tes including est	imated date
of starting any proposed wo						
proposed completion or rec		· · · · · · · · · · · · · · · · · · ·	i or manupie co	imprecions. Traden	wonoore diagram	
	'					
Perfs 5113' – 5389'				,		_
Plan to POOH with production equip			070 + Dump ba	il 35' of cement or	top of the CIBP	, load the
casing with pkr fluid & pressure test	the casing to 500 psi for 32	2 minutes.				
			Conditio	n of Approval:	notify	
COA SUDMIT WELLBODE DIACDAM				·		
OCD I				obbs office 24 hours		
· · · · · · · · · · · · · · · · · · ·	-		prior of rui	ning MIT Test	& Chart	
· · · · · · · · · · · · · · · · · · ·			-			
Spud Date:	Dia D	elease Date				
Spud Date.		cicase Daic	···			
I hereby certify that the information	1 1 1	to the bes	t of my knowledg	a and baliaf		
Thereby certify that the information		to the bes	i oi iiiy kiiowieug	e and benen.		
0	above is true and complete		,			
	above is true and complete					j
SIGNATURE	above is true and complete	E Instr	ument Tech	D	ATE 12-5	-14
SIGNATURE	TITLI		ument Tech	D	OATE 12-5	-14
Type or print nameJim Ellison_	TITLI		ument Tech	Dacheccorp.com_ Pl	HONE: 441	-14 -7734
	TITLI		ument Tech	Dacheccorp.comPI	HONE: 441.	-14 -7734
Type or print nameJim Ellison_ For State Use Only	TITLI		ument Tech	acheccorp.com_PI	ATE 12-5 HONE: 441-	-14 -7734 -7014
Type or print nameJim Ellison_ For State Use Only APPROVED BY:	TITLI		ument Tech	acheccorp.com_Pl	ATE 12-5 HONE: 441- ATE 12/8/2	-14 -7734 2014
Type or print nameJim Ellison_	·		ument Tech	acheccorp.com_PI	ATE 12/8/2	-14 -7734 2014