

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-05145

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

T. D. Pope

8. Well Number

10

9. OGRID Number

227103

10. Pool name or Wildcat

Denton: Devonian (16910)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Platinum Exploration Inc

3. Address of Operator

550 W. Texas, Suite 500 Midland, TX 79701 432-687-1664

4. Well Location BHL I 2310

South

330

East

Unit Letter P : 660 feet from the South line and 660 feet from the East line

Section 26 Township 14S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3805' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: Run new pump ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/12/05-12/30/05

MIRU PU, Unable to free pump, pump 190 Bbl to fill up, work tbg. RU Key pump truck on csg - 3 Bbl to load. Unable to pump past sub pump, work tbg. RU WL truck, run free point, free @ 11,025'. RIH w/ jet cutter. 11,025', cut tbg and work cut tbg free. POOH w/ 229 jts & stub 20.89' of 2 7/8" RIH w/ 2 5/8" OD Concave mill, sub, jars & 4 - 3 1/2" DC, XO, SN & 166 jts 2 7/8" tbg, RIH tag @ 1105'. RIG up rev unit, milled to 11007'. Cir clean, POOH & std 2 7/8 tbg MI & rack new tbg. PU off rack and RIH 2 7/8" EUE 8rd tbg. Total of (229 jts in hole). SN @ 7502.50'. Pour new rope socket & RU swab. 1st run FL @ 400' from surface last run FL @ 6900' from surface - recover 138 bbls. RD swab, RIH w/ PH6. Tag fish @ 11008'- Unable to latch. RU swivel and Worked OS over fish, latch up & work fish up 35'- 25' of movement, Fish came free. POOH RU swab tag FL @ 4300' FS. RU Weatherford acid & pmped 12 Bbl of 15% HCL NEFE, pmp 34 Bbl PW. Stnd by for 30 min. POOH, acid up on tbg 100' on back side. PU 4 7/8" OD OS. Cut dwn to 4 5/8" OD w/ fluid guide, 4" ID w/ 4" grapple, bumper sub, jar, 4 - 3 1/2" OD DC XO SN. RIH. Tag @ 11010'. RU swivel, dress off fish, latch fish, spud dwn, pulled up 35K over - unable to make hole up or dwn. Pmp 110 Bbl wtr @ 2 BPM. Worked fish, pmp 90 Bbl, work fish - unable to get mvmnt. RU swab line & RIG. Tag FL @ 3400' FS. RU acid truck, pmp 12 Bbl acid, 36.4 Bbl wtr, work fish, jarred up 25K over. PU on tbg- Fish was free, pulled up 60', stuck, work fish free. POOH, PU Swivel tag @ 11953', milled 1.5', lost cir, Pmp went DH. PU tbg, RIH & tag @ 11,813'. Milled 5' TOF @ 11,818'. Cir clean POOH PU 4 5/8 shoe w/ WP & top bushing 37' jar 4 31 V2. DC XO SN. RIH w/ 333 jts.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Debbie Freeman TITLE Agent DATE 1/18/06

Type or print name Debbie Freeman E-mail address: debbief@t3wireless.com Telephone No. 432-687-1664

For State Use Only

APPROVED BY: Gayle W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 24 2006

Conditions of Approval (if any):

TD POPE 26-10 Cont. C103

1/3/06-1/9/06

POOH, RIH w/ 348 jts 2 7/8" tbg. RU swivel, Rotated over fish, unable to latch fish. Tag @ 11,817.96'. POOH, OS was full of cable. PU new 4 7/8" latch up & work 4 jts out of hole. POOH w/ 170 jts. RIH w/ 362 jts 2 7/8" tbg. RU rev unit Tag @ 11,908'. Milled 3.5', fell free to 11,976'. POOH PU TD 3000 ESP sub pump.
RD & clean loc.