

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31707
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-155
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	78
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4005'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>E</u> : <u>2491</u> Feet From The <u>North</u> Line and <u>127</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4005'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ISOLATION PKR - TA WELL ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-16-06: MIRU. REL PKR.

3-17-06: MOVE IN 205 JTS WS. PU BIT & WS TO TAG @ 5650. WORK BAILURE FR 5650 TO 5720. FELL THRU. TAG UP@ 5933. NO CIBP @ 5770. BOT @ 2508.

3-21-06: TIH W/BIT, BIT SUB, STRING MILL, 185 JTS 2 7/8" WS. WORK MILL @ 5705 TO 5711 UPPER LATERAL & 5741-5747 LOWER LATERAL. RUN MILL TO 5770 & BIT TO 5833 W/187 JTS. TIH W/RBP & SET @ 5730. PKR @ 5721. PMP 120 BBLS DN TBG. PUSH RBP DN HLE. LATCH ON. PULL UP TO 5563.

3-22-06: LOWER RBP & PKR TO 5754. TIH W/RETR HEAD & 185 JTS. TAG TOP OF RBP @ 5746. ATTEMPT TO LATCH. PU SWIVEL ROTATED & PMP 2% KCL DN TBG. TOH W/105 JTS TO 2500.

3-23-06: TIH W/RBP RETR HEAD W/CUT LIP GUIDE & 185 JTS TBG TO TOP OF RBP @ 5746. PMP WATER DN TBG TO ENGAGE. TOH W/80 JTS TO 3112.

3-24-06: TIH W/SHORT CATCH OS W/GRAPPLE, 185 JTS. TAG TOP OF FISH @ 5746. ENGAGE FISH. PULL 40 OVER. ROTATE. COULDN'T REL. PULL 65 OVER. JAR & TURN LOOSE. TIH W/BIT & WS & TAG @ 5724. TOH TO 5610.

3-27-06: TIH W/SHORT CATCH & TAG @ 5726. PUSH DN TO 5762. TIH W/RBP & SET @ 5730. PULL 20 OVER & SET DN 20 POINTS. TOH W/RBP & TBG TO 2489' 80 JTS IN HOLE.

3-28-06: TIH W/PKR & SET @ 5722. REL PKR & RBP. ATTEMPT TO SET RBP @ 5734. TOH. TIH W/OS & TAG @ 5762. TOH TO 2500.

3-29-06: TIH W/OS TO 5762. TAG TOP OF WHIPSTOCK PKR. PULLED UP. WORK INTO LOWER LATERAL. WINDOW @ 5741. PUSH DN TO 5770. TIH W/RBP & PKR. SET RBP @ 5624. PULL PKR UP. TIH W/RBP @ 5624. TEST CSG TO 520# 15 MINS. NO LOST.

3-30-06: LATCH ON TO RBP & RELEASE. TIH W/CIBP & SET @ 5624. CIRC W/125 BBLS 10# BRINE PKR FLUID. PRE TEST TO 550# 20 MINS. NO LOST.

3-31-06: CHART & TEST FOR NMOCD - 520# FOR 35 MINS. GOOD. (ORIGINAL CHART & COPY OF CHART ATTACHED). RIG DOWN. FINAL REPORT

WELL IS TA'D

This Approval of Temporary
Abandonment Expires 3/31/11

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist

TYPE OR PRINT NAME Denise Pinkerton

APR 12 2006
Telephone No. 602-687-7375

(This space for State Use)

APPROVED Ray W. Wink
CONDITIONS OF APPROVAL, IF ANY: TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

APR 12 2006

