

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
HOBBS OGD
 OIL CONSERVATION DIVISION
 AUG 16 2018
 300 South St. Francis Dr.
 Santa Fe, NM 87505
RECEIVED

Form C-103
 Revised August 1, 2011

WELL API NO. 30-025-28363	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit	
8. Well Number 160	
9. OGRID Number: 157984	
10. Pool name or Wildcat: Hobbs (G/SA)	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3607.7' (RDB)	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
P.O. Box 4294, Houston, Tx 77210

4. Well Location (Surface)
 Unit Letter G : 2475 feet from the North line and 2425 feet from the East line
 Section 9 Township 19S Range 38E NMPM Lea County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p style="text-align: center;">NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/></p> <p>OTHER: <input checked="" type="checkbox"/> OAP/DPN/Acidize</p>	<p style="text-align: center;">SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>
---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU PU. ND Wellhead. NU BOP.
 - 2) POOH with ESP
 - 3) Trip a bit and drill well to new TD at 4365' (casing shoe at 4315')
 - 4) Selectively perforate San Andres from 4158'-4304' at 4 SPF
 - 5) Stimulate wellbore with 8,000 gal 15% HCL
 - 6) Set RBP at ±3900' and ±1000' and prepare well for wellhead change
- Following wellhead change:
- 7) MIRU PU; Pull plugs
 - 8) RIH with ESP
 - 9) ND BOP. NU Wellhead. RDMO PU. RTP Well

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jacob S. Cox TITLE Production Engineer DATE 08/15/2018

Type or print name Jacob S. Cox E-mail address: Jacob_Cox@oxy.com PHONE: 713-497-2053

For State Use Only
 APPROVED BY: Maley & Brown TITLE AO/I DATE 8/16/2018
 Conditions of Approval (if any):

MB