Office	State of New Mexico	Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONCEDIVATION DIVISION	30-025-30306	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505 OCD	6. State Oil & Gas Lease No. 313857	
87505	ICES AND REPORTS ON WELLS . 2 2019		
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	SALS TO DRILL OR TO DEEPEN OR PARK EACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH.	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT	
1. Type of Well: Oil Well	Gas Well Other INJECTOR	8. Well Number 151	
2. Name of Operator RAM ENERGY LLC		9. OGRID Number 309777	
3. Address of Operator		10. Pool name or Wildcat	
2100 S. UTICA AVE., SUITE	175, TULSA, OK 74114	DOLLARHIDE QUEEN (018810)	
4. Well Location			
Unit Letter M_:	550 feet from theWEST line and499		
Section 29	Township 24S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, etc.,	NMPM LEA County	
	3180' KB		
-	-		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRI	LLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE			
OTHER:	☐ OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
proposed completion of re-			
1. NOTIFY NMOCD 24 HRS. BEFORE MIRU.			
1. NOTIFY NMOCD 24 HRS	2. MIRU. ND WH, NU BOPE.		
<ol><li>MIRU. ND WH, NU BOP!</li></ol>		ייייייייייייייייייייייייייייייייייייי	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32	250'. (PERFS)	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 .F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT	ES/B.SALT)	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA	ES/B.SALT) LT)	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> <li>SPOT 50SX OF CLASS "C</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE).	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> <li>SPOT 50SX OF CLASS "C</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE).	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> <li>SPOT 50SX OF CLASS "C</li> <li>CUTOFF WELLHEAD, A RECLAMATION.</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> <li>SPOT 50SX OF CLASS "C</li> <li>CUTOFF WELLHEAD, A RECLAMATION.</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR	
<ol> <li>MIRU. ND WH, NU BOP!</li> <li>SET CIBP@3600' AND S!</li> <li>CIRCULATE 9.5 PPG ML</li> <li>SPOT 30SX OF CLASS "C</li> <li>SPOT 25SX OF CLASS "C</li> <li>SPOT 50SX OF CLASS "C</li> <li>CUTOFF WELLHEAD, A RECLAMATION.</li> </ol>	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 IF AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:	es/B.salt) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.	es/B.salt) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 IF AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva e and belief.	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAINATE  Spud Date:  I hereby certify that the information  SIGNATURE	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEMENCHORS 3' BELOW SURFACE AND INSTALL DR  NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva  e and belief.  AGERDATE05/22/19	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAINATE  Spud Date:  I hereby certify that the information  SIGNATURE	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEME NCHORS 3' BELOW SURFACE AND INSTALL DR NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:  above is true and complete to the best of my knowledge	ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva  e and belief.  AGERDATE05/22/19	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name MATTHEW PA For State Use Only	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEMENCHORS 3' BELOW SURFACE AND INSTALL DR  NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:  TITLE OPERATIONS MAN TITLE OPERATIONS MAN TITLE OPERATIONS MAN	ES/B.SALT) LT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva  e and belief.  AGERDATE05/22/19 ENERGY.NET_PHONE: _(918)947-6301_	
2. MIRU. ND WH, NU BOP! 3. SET CIBP@3600' AND S! 4. CIRCULATE 9.5 PPG ML 5. SPOT 30SX OF CLASS "C 6. SPOT 25SX OF CLASS "C 7. SPOT 50SX OF CLASS "C 8. CUTOFF WELLHEAD, A RECLAMATION.  CLOSED LOOP CONTAI  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name MATTHEW PA For State Use Only	POT 25SX OF CLASS "C" CEMENT FROM 3600'-32 F AND TEST CASING. C" CEMENT FROM 2830'-2580'. WOC&TAG. (YAT C" CEMENT FROM 1328'-1128'. WOC&TAG. (T.SA C" CEMENT FROM 466'-SURFACE. VERIFY CEMENCHORS 3' BELOW SURFACE AND INSTALL DR  NMENT SYSTEM WILL BE USED FOR FLUIDS.  Rig Release Date:	ES/B.SALT) LT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR  See Attached Conditions of Approva  e and belief.  AGERDATE05/22/19 ENERGY.NET_PHONE: _(918)947-6301_	

## WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #151

Created: Well #: 05/22/19 By: LEE R. 151 Updated: By: API 30-025-30306 Lease: WEST DOOLARHIDE QUEEN SAND UNIT Unit Ltr.: М 29 Sec. Field: QUEEN TSHP/Rng: 24S-T38E 550' FWL & 492' FSL Pool Code: OGRID: Surf. Loc.: 309777 Bot. Loc.: NM County: LEA St.: **Directions:** Status: Surface Casing Size: 8-5/8" Wt., Grd.: 24# Depth: 416 Sxs Cmt: 250 Circulate: yes TOC: surface Hole Size: 12-1/4" FORMATION TOPS T.Salt 1228' EST. B. Salt 2780' EST. Intermediate Casing Size: 5-1/2" Queen: 3656'-3808'(OA) Wt., Grd.: 15.5 Depth: 3940'

Sxs Cmt:

Circulate:

Hole Size:

TOC:

1000

YES

SURFACE

7-7/8"

## WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #151

Created: 05/22/19 By: LEE R. Well#: 151 Updated: By: API 30-025-30306 Unit Ltr.: Lease: WEST DOOLARHIDE QUEEN SAND UNIT М 29 Sec. QUEEN Field: TSHP/Rna: 24S-T38E Surf. Loc.: 550' FWL & 492' FSL Pool Code: OGRID: 309777 Bot. Loc.: LEA NM Directions: County: St.: Status: Surface Casing Size: 8-5/8" Wt., Grd.: 24# Depth: 416 Sxs Cmt: 250 Circulate: yes TOC: surface Hole Size: 12-1/4" SPOT 50SX OF CMT FROM 466'-SURFACE. **VERIFY. (FW/SHOE/SURFACE) MLF** SPOT 25SX OF CMT FROM 1328'-1128'. WOC&TAG. (T.SALT) MLF FORMATION TOPS T.Salt 1228' EST. SPOT 30SX OF CMT FROM 2830'-2580'. B. Salt 2780' EST. **MLF WOC&TAG. (YATES/B.SALT)** SET CIBP@3600' AND SPOT 25SX ON TOP Intermediate Casing FROM 3600'-3250'.(PERFS) Size: 5-1/2" Queen: 3656'-3808'(OA) Wt., Grd.: 15.5 Depth: 3940' Sxs Cmt: 1000 Circulate: YES TOC: SURFACE

Hole Size:

7-7/8"

## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.