	UNITED STATES EPARTMENT OF THE INTI				OMBN	APPROVED IO. 1004-0137 January 31, 2018	
HOBES OCD B B B B B B B B B B B B B B B B B B B	UREAU OF LAND MANAGE NOTICES AND REPORT is form for proposals to dri II. Use form 3160-3 (APD) f	Saris	bad Fi	eld Of	5. Lease Serial No.	anuary 51, 2010	
AUG 2. Do not use the	obbs	6. If Indian, Allottee	or Tribe Name				
	TRIPLICATE - Other instruc					ement, Name and/or No.	
1. Type of Well						8. Well Name and No. SAND CHUTE 4/9 B2AP FED COM 1H	
2. Name of Operator MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com					9. API Well No. 30-025-46061-00-X1		
a. Address P O BOX 5270 HOBBS, NM 88241	include area code) 10. Field and Pool or Exploratory Area 5905 PEARL						
Location of Well (Footage, Sec., 7	T., R., M., or Survey Description)			11. County or Parish, State			
Sec 4 T20S R35E 205FNL 66 32.609039 N Lat, 103.455856		LEA COUNTY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICAT	TE NATURE O	F NOTICE, I	EPORT, OR OT	HER DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION			
□ Notice of Intent	Acidize	🗖 Deep	en	Productio	on (Start/Resume)	□ Water Shut-Off	
	Alter Casing	🗖 Hydr	aulic Fracturing	Reclamation		U Well Integrity	
Subsequent Report	Casing Repair	🗖 New	Construction	Recomplete	ete	🛛 Other Well Spud	
Final Abandonment Notice	Change Plans Pl		and Abandon Back	Temporarily Abandon Water Disposal		wen spuu	
Spud 17 1/2" hole @ 1865'. R (35:65:10) w/additives. Mixed 14.8#/g w/1.32 yd. Displaced the pit. Test BOPE to 5000# 8 mins, held OK. FIT test to 10.3	@ 12.9#/g w/1.88 yd. Tail w/ w/279 bbls BW. Plug down @ & Annular to 3500#. At 4:30 P	/200 sks Cl 5:00 AM 9.M. 06/15/	ass C w/additive 06/14/19. Circ 3	es. Mixed @ 85 sks of cm	t to		
Charts & Schematic attached.							
Bond on file: NM1693 nationw	vide & NMB000919						
	Electronic Submission #477 For MEWBOURN nmitted to AFMSS for processi	IE OIL CO M	PÁNY, sent to ti CILLA PEREZ or	ne Hobbs	•	<u></u>	
Name (Printed/Typed) RUBY CA	BALLERO		Title CLERK		<u></u>	·····	
			Date 08/09/20				
Signature (Electronic S	THIS SPACE FOR	FEDERA			E		
Signature (Electronic :		T					
Signature (Electronic S			Title Accer	oted for	Record	AUG _{at} 2 0 201	
	d. Approval of this notice does not uitable title to those rights in the sub		Jor	oted for in nathon She Isbad Field (pard	AUG _{at} 2 0 201	
pproved By ditions of approval, if any, are attache ify that the applicant holds legal or equ	d. Approval of this notice does not uitable title to those rights in the sub uct operations thereon. U.S.C. Section 1212, make it a crim	pject lease ne for any per	Jor Car Office	athon She Isbad Field C	pard Office	AUG _{at} 2 0 201	









.



Lease: <u>S</u> Plug Size	Mechouche Mechouche and Chube 419 BZAPF atype: 12" 3 CERT	Lo Lo Lo Lo Lo Lo Lo Lo Lo Lo	UP SERVIC MUD AND G vington, NI Date: (Drilling ze (3AS SEPARA M • 575-3 2-15- Contractor 39	FTS • TANDEM ATORS 398-4540 Pg of -/9 Involce # pr:Rig # Tester:Rig #
-	Cosing Valve Must Be Open During BOP Test *		Ingsta	ined GOP	* Check Valve Must Be Open/Disabled To Test Kill Line Valves *
		#26 #2 #4 #4 #3 #1 #1 #2 #3 #1 #2 #3 #1 #2 #2 #4 #3 #1 #2 #2 #4 #3 #1 #2 #2 #4 #3 #1 #2 #4 #3 #4 #4 #3 #4 #4 #3 #4 #4 #4 #4 #4 #4 #4 #4 #4 #4 #4 #4 #4	#5 #88 Mud Gaug Valve	#6 1 1 3 9 9	BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #17 BOP #12 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 BOP #1 B
TEST +	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
1	Tack test	10/10	250	5K	1255
2	25,26,6	Burg	-	5K	PESS
3	14,2021,22,23	10/10	zso	SIC	Pass Pass Pass Pass Pass
4	129 24 26 186	10/10	250	SK	Pass
5	12,10,17,345.86	610	750	SK	Pass
6	12/11/6.8	10110	250	SK SK	DES
7	12,11,18.7	10/10	250	SK	DESS 1
8	129 24 26 186 12,10,17,34586 12,11,16,8 12,11,16,8 12,11,18,7	10/10	250	35æ 5k	ner 1
9	19	10/10	250	SK	pest
10	13,71,34,5	10/10	250	SK	pess pess pess pess

/1

.

MAN WELDING SERVICES, W
MAR
Company Mubourne Date 6-15-19
Company Mubourne Date 6-15-19 Lease Sand Chute 4/9BRAP County Lease
Drilling Contractor Reflecten S62 Con Plug & Drill Pipe Size 12" STCT39
Accumulator Pressure: 300 Manifold Pressure: 1500 Annular Pressure: 1500
Accumulator Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
 Make sure all rams and annular are open and if applicable HCR is closed. Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
1. Open HCR Valve. (If applicable)
2. Close annular.
3. Close all pipe rams.
4. Open one set of the pipe rams to simulate closing the blind ram. 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
6. Record remaining pressure // S psi. Test Fails if pressure is lower than required.

- a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system }
- 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop <u>1300</u> psi. Test fails if pressure drops below minimum.
- Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off value to the tank, {manifold psi should go to 0 psi} close bleed value.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time 1. w. lose. Test fails if it takes over 2 minutes.
 - a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}