Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240			May 27, 2004 L API NO.	
District II	OIL CONSERVATION D	20.00	5-23525	
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		dicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV			6. State Oil & Gas Lease No. E-2431	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ICES AND REPORTS ON WELLS		ase Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLI	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Gulf State Com	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		ell Number	
2. Name of Operator			GRID Number	
C. W. Trainer		3474	1	
3. Address of Operator P. O. Box 754, Midland, Texas 75	9702		ool name or Wildcat on Wolfcamp, East	
4. Well Location				
Unit Letter A:	660feet from the _North	line and	660 feet from the East line	
Section 4	Township 15S Range	35E NMP	M County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4004.2 GL				
řii or Beiow-grade Tank Application 🔲 (
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON RECHANGE PLANS CO	SUBSEQUEMEDIAL WORK DIMMENCE DRILLING ASING/CEMENT JOB	JENT REPORT OF: ALTERING CASING OPNS: P AND A	
			<u></u>	
OTHER:		THER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Ran in the hole with a gauge ring to 10,505'. Came out of the hole with gauge ring and went in the hole with CIBP and set at 10,454' **Mark pressure Left to 500 psc and submit original clear to Hole dislut of five Cult in the hole with CIBP and set at 10,454' **Position of the hole with gauge ring and went in the hole with CIBP and set at 10,454' **Position of the hole with gauge ring and went in the hole with CIBP and set at 10,454'				
Ran in the hole with a gauge ring to 10,505'. Came out of the hole with gauge ring and went in the hole with CIBP and set at 10,454'				
Came out of the note with gauge in	ig and went in the hole with CIBF and	set at 10,434	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
	T. A.T. Ennes	\mathcal{L}_{l}	E De l'or	
must pressure	Took to 500 psi on . chart to Hobbe distu		62 66 62 66 66 66 66 66 66 66 66 66 66 6	
so but orisinal	chart to Hobbe destu	soffee Cll	1 2008 MM 33	
sear har organis	, .	00	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	
I hereby certify that the information	shove is two and complete to the heat of			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.				
SIGNATURE Mey C	7. JONES TITLE A	gent for CW Trainer	_DATE12/27/06	
Type or print name For State Use Only Sheryl L.		s4011@aol.com T	Celephone No.432-683-5511	
APPROVED BY: Conditions of Approval (if any):	Others OCHERICA	SUPERVISOR/GENER	AL MANAGIDATE JAN 0 4 2007	