Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires January 31, 200

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

5. Lease Serial No.

1. Type of Well Oil Well X Gas Well Other 2. Name of Operator GRUY PETROLEUM MANAGEMENT COMPANY 3a. Address p.o. box 140907, IRVING, TEXAS 75014-0907 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT LETTER D 660' FNL & 660' FWL 38. W CART 3b. Phone No. (include area code) 30-(10. JAIN TAN.	Vell Name and No. I.SON HARRISON ERAL COM. #002 PI Well No. 025-11810 Field and Pool, or Exploratory Area
3a. Address p.o. box 140907, Irving, Texas 75014-0907 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT LETTER D 660' FNL & 660' FWL 3b. Phone No. (include area code) 469-420-2728 10. TAN. 11.	API Well No. O25-11810 Field and Pool, or Exploratory Area
SEC 27, T-25-S, R-37-E	County or Parish, State
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent Acidize	Well Integrity Other

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

CRUY PETROLEUM MANAGEMENT CO. REQUESTS APPROVAL TO PLUG AND ABANDON THE SUBJECT WELL PERF BLM SPECIFICATIONS AS PER THE ATTACHED PLUGGING PROCEDURE. IF YOU SHOULD HAVE ANY QUESTIONS OR COMMENTS PLEASE CONTACT DAVID EYLER AT 432-687-3033.



46.000				
14. I hereby certify that the foregoing is true and correct Name (Printed Typed)	Title			
DAVID A. EYLER	ACENT			
Daniel A. E. Q	Date 09/15/03			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject leads to which would entitle the applicant to conduct operations thereon.	or Office			

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Gruy Petroleum Management Company Carlson Harrison Federal Com 002

A.P.I. #: 30-025-11810

Lease Serial #:

Field: Jalmat: Tan-Yates-7 Rvrs

Location: 660' FNL & 660 FWL, Unit Letter D, Sec. 27, Twp. 25S, Rge. 37E

Lea County, New Mexico

Completion Date: 1956

Total Depth:

3,542' P.B.T.D.: 2,665' (CIBP @ 2700' w/ 35' cement)

Casing Data:

9-5/8" 32.3# H-40 @ 300' w/ 250 sxs. – TOC = Surface 7" 23# @ 3537' w/ 300 sxs. – TOC = N/A (DV Tool @ 926')

Tubing Data:

None.

Rod Data: Open Perfs:

None

Remarks:

Perf. 3340'-3450' (CIBP @ 3310'), Perf. 2880'-2950' & 2965-3040' (CIBP @

2700' w/35' cement.

09/24/91: Sqz. csg. leaks @ 454'-485' w/ 150 sxs. cmt. - Circ. to surface.

PXA PROCEDURE

1) MIRU workover rig, 2700' workstring & PXA equipment.

- 2) PU & RIH w/ tubing OE to 2665'; Circulate well w/ 9.5# salt gel mud; POOH laying down tubing to 1000'; Mix & pump a 30 sx. class "C" cmt. plug @ +/-1000'; POOH laying down tubing to 400'; Mix & pump a 60 sx. class "C" cmt. plug @ 200'-400'; POOH w/ tubing & WOC; RIH w/ tubing & tag top of cmt. plug.
- 3) POOH laying down tubing to 63' & mix & pump a 15 sx. cmt. surf. plug @ 3'-63'. FOOH w/ tubing.
- 4) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 5) RDMO rig and PXA equipment. Clean location.

