

MAY 2 3 2008

Final Abandonment Notice

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HO	BBB

FORM APPROVED

		Expires: March 31, 200
·	~	

6 If Indian, Allottee or Tribe Name

Ø		SUNDRY NOTICES not use this form for andoned well. Use Form	AND F	REPORTS	ON WELLS
-		notuse this form for	proposal	ls to drill o	r to re-enter an
U	J. J. Jab	ầnđoĥểd well. Use Fori	m 3160	3 (APD) for	such proposals.

Convert to Injection

5 Lease Senal No. Fee. SW 876NM71874

Tabandoned w	rell. Use Form 3160-3 (/	APD) for such pro	oposals.	BLM
SUBMIT IN TR	NPLICATE- Other insti	ructions on revei	rse side.	7. If Unit or CA/Agreement, Name and/or No.
l Type of Well	Gas Well Other			8. Well Name and No.
2 Name of Operator Xeric Oil&Ga	s Corp			Crosby Deep 2 9. API Well No.
3a Address		3b Phone No (include	,	30-025-24287
P.O. Box 7288 Ode	essa Tx 79760	432-64-09	81	10 Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)			Crosby Deep Fusselman	
330 FSL +	1980 FWL			11 County or Parish, State
Sect 33 T 25S R	37E Uni76			Lea Co NM
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	LE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION	
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Sta	water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	Temporarily Ab	pandon

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Water Disposal

Plug Back

This is a TA oil well. We will make sure electricity is established. Move a 114 pumping unit and set. Check well head for pressure or leaks, bleed off well with a BOP, stand by if well is dead, pull rod & D hole pump, send pump in for a redress TOH with tubing run sinking bar totd trip in hole with tubing, hydro testing and replace any bad joints, TIH with rod & pump niple up with pumping tee, cut well on

After 8-20-08 the well must be online or plans to P & A must be submitted.

NOTIFY WHEN WELL IS BACK ON Prod.

CARLSBAD FIELD OFFICE

14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)		
Walter E King	Title Agent for Xeri	c Oil & Gas Corp
Signature 11)		
Jan Vallety	Date	ADDDOVED
THIS SPACE FOR FEDERA	L OR STATE OFFICE USE	I APPRUVEU
Approved by /// OC DISTRICT SUPERIOR	VISOR/TUIENERAL MANAGER	Date
Conditions of approval, if any, are attached. Approval of this notice does not warri- certify that the applicant holds legal or equitable title to those rights in the subject I which would entitle the applicant to conduct operations thereon.	ant or	MAY 2 0 2008 /s/ JD Whitlock Jr
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an States any false, fictitious or fraudulent statements or representations as to any matter.	y person knowingly and willfully to make to a er within its jurisdiction.	
(Instructions on page 2)		OADLODAD FIELD OFFICE