• •	
Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resource	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II OIL CONSERVATION DIVISIO	N <u>30-025-33377</u>
1301 W Grand Ave, Artesia, NM 88210 District III	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fein 118,7508	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 2 3 20	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM(C-101) HORSOGH PROPOSALS.)	Teague 2 State -
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
XTO Energy, Inc. /	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. Loraine, Ste. 800 Midland, TX 79701 4. Well Location	Teague; Paddock, Blinebry
Unit Letter <u>E</u> : <u>1650</u> feet from the <u>North</u> line and <u>330</u> feet from the <u>West</u> line	
Section 2 Township 24S Range	37E NMPM County Lea
11. Elevation (Show whether DR, RKB, RI	r, GR, etc.)
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; (	
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	E DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TE COMPLETION CASING TE	
OTHER: Stimulate 🛛 OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>	
1. RUPU. Pull rods & pump. Install BOP. Tag TD. 2. TIH w/ 4-3/4" bit & WS. Clean out well to 5613'. Circ clean & POH. 3. TIH w/ Sonic Hammer on WS. RU stripping head. 4. RU acid company & sonic hammer OH w/9# brine while circ. Circ hole clean. Close in backside & sonic	
hammer OH w/5000 gals 20% acid in inj mode. 500# max on backside. Flush acid w/30 bbls 9# brine.Drop ball to shift sleeve in tool.	
<ol> <li>Open well back to pit thru 8/64". Let well flow dwn &amp; open another 8/64ths. Rig up swab load back.</li> <li>POH w/Sonic Hammer. TIH w/tbg &amp; st SN below perfs. TIH w/rods &amp; pump. RWTP.</li> </ol>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE SIGNATURE TITLE Regulatory Analyst DATE 4/22/2008	
UE-mail address:Type or print nameSherry Pack	sherry_pack@xtoenergy.com Telephone No. 432.620.6709
APPROVED BY China Williams OC DISTRICT SUPERVISOR CENERAL MANAGER DATE MAY 2 7 2008	
Conditions of Approval, if any: must be leved pit or steel frace tank . and	

.



.

-4