

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-27992
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Marks and Garner Production Ltd. Co.		6. State Oil & Gas Lease No. E3145
3. Address of Operator P.O. Box 1089, Hobbs, NM 88241		7. Lease Name or Unit Agreement Name: Coquina State
4. Well Location Unit Letter <u>H</u> 1980 feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>19</u> Township <u>21S</u> Range <u>35E</u> NMPM Lea County		8. Well No. 1 9. Pool name or Wildcat San Simon, Yates North (Assoc)
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Set CIBP @ 3650' and cap with 35' cement.
Circulate casing with mud gel brine.
Spot 5 sx plug at surface.
Cut off wellhead 3' below surface.
Weld on dry hole marker.
Clean Location.

THE OIL CONSERVATION DIVISION MUST BE
NOTIFIED 24 HOURS PRIOR TO THE BEGINNING
OF PLUGGING OPERATIONS

RECEIVED

JUL 23 2008
HOBBS OCD
DENIED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debbie M Kelly TITLE AGENT DATE 7/21/08

Type or print name Quinton Welborn Telephone No. 575-393-9358

(This space for State use)

APPROVED BY: _____ TITLE _____ DATE _____
Conditions of approval, if any: