

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised June 10, 2003

WELL API NO.

30-025-08128-00-00

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

10852

7. Lease Name or Unit Agreement Name
James Federal

8. Well Number

001

9. OGRID Number

22223

10. Pool name or Wildcat

Trieste Draw

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

TEMPO ENERGY, INC.

3. Address of Operator

PO BOX 1034 MIDLAND, TX 79702

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the East line

Section 35

Township 23S

Range 32E

NMPM

County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU- DIG & LINE WORKING PIT- POOH WITH TUBING
2. SET CIBP @ 4900'- SPOT 15 SXS CEMENT ON TOP- CIR. 10# MUD
3. FREEPOINT CASING- CUT & LAY DOWN
4. SPOT 35 SXS @ STUB & TAG - 50' IN & 50' OUT & TAG
5. SPOT 40 SXS @ SHOE - TAG
6. SPOT 10 SXS @ 60' TO SURFACE
7. CUT OFF WELL HEAD, ANCHORS & INSTALL DRY HOLE MARKER
8. LEVEL PIT & CELLAR- MOVE OUT

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 10/27/03

Type or print name JIM PANNELL E-mail address: jimpannell@cox.net Telephone No. (432) 689-2951

(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 03 2003

Conditions of approval, if any