Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135

	Expires: July 31, 20
5.	Lease Serial No.
	NMNM54432

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter

abandoned we	II. Use form 3160-3 (API	D) for such i	foposals \	6. If Indian, Allo	ttee or Tribe Name	
	PLICATE - Other instruc		17.5		Agreement, Name and/or No	
I Type of Well  ☑ Oil Well ☐ Gas Well ☐ Oth		8. Well Name and MARK FEDE				
Name of Operator     READ & STEVENS INCORPO	Contact: DRATEDE-Mail: dluna@rea		9. API Well No. 30-025-321	58-00-S1 🗸		
3a. Address P O BOX 1518 ROSWELL, NM 88202		Ph: 575-62 Fx: 575-622	(include area cod 2-3770 Ext: 21 -8643		ol, or Exploratory  GE  Llaware: NE	
4. Location of Well (Footage, Sec., 7		i)		11. County or Pa	rish, and State	
Sec 3 T20S R34E NESE 1650	UFSL 33UFEL	$\checkmark$		LEA COUN	TY, NM 🗸	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	I NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
□ Notice of Intent	☐ Acidize	□ Deep	oen	Production (Start/Resume	e) Water Shut-Off	
Subsequent Report	☐ Alter Casing	□ Frac	ture Treat	□ Reclamation	☐ Well Integrity	
	Casing Repair		Construction	Recomplete	Other	
☐ Final Abandonment Notice	Change Plans	_	and Abandon	Temporarily Abandon		
13 Describe Proposed or Completed Op	Convert to Injection	□ Plug		□ Water Disposal		
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed Final A determined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide disperations. If the operation re bandonment Notices shall be fil	, give subsurface the Bond No. o sults in a multir	locations and mean file with BLM/B le completion or re	asured and true vertical depths of all BIA. Required subsequent reports sleep and a new interval a Formulation in a new interval.	I pertinent markers and zones hall be filed within 30 days	
10/22/08						
MIRU Mayo Marrs. BLM notif plugging mud to surface. SW	ied but not present at loca IFN.	ation. PU&F	IH w/tbg to 5,3	01'. Circ		
10/24/08						
Pull tbg to 3,937'. Spot 35 sxs	s cmt w/2% CaCl. POH &	WOC. RIH	v/tbg and tag a	t 3,772'. Spot 25		
14. I hereby certify that the foregoing is	true and correct					
	Electronic Submission #6 For READ & STE	VENS INCORE	ORATED sent	II Information System to the Hobbs 10/31/2008 (09KMS0033SE)		
Name(Printed/Typed) DAVID LU			Title ENGIN	•		
Signature (Electronic S	ubmission)		Date 10/30/2	2008		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE USE		
Approved By ACCEPT	ED Sul	/	JAMES A TitleSUPERVI		Date 11/01/20	
onditions of approval, if any, are attache ertify that the applicant holds legal or equal which would entitle the applicant to condu	not warrant or e subject lease	Office Hobbs		2008		

## Additional data for EC transaction #64302 that would not fit on the form

## 32. Additional remarks, continued

sxs cmt on top of plug. POH & WOC. RIH & tag cmt at 3,772'. Spot 25 sxs cmt w/2% CaCl. POH & WOC. RIH & tag plug at 3,024'. POH LD tbg and spot 25 sxs cmt at 1,550'. POH & WOC. RIH & tag plug at 1,247'. POH w/tbg. NDBOP. RIH to 60' and circ 20 sxs cmt to surface. Dig out and remove wellhead. Cut anchors. Install dryhole marker. RDMO pulling unit. Level location. Well plugged and abandoned at report time.

Read & Stevens, Inc. will submit final abandonment notice once lease is ripped and reseeded per BLM guidelines.