Submit 3 Copies To Appropriate District Stat	te of New Mexico	Form C-103
Office Energy, Min	erals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88220 C		WELL API NO. 30-025-22039
District II 1301 W Grand Ave., Artesia, NM 88210 OIL CONS	SERVATION DIVISION	5. Indicate Type of Lease
District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd. Aztec, NM 87410	South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Sar	nta Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NDBBSOCD		
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement National Control of the Cont		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH S		Simmons
DDODOCALC)		8. Well Number 002
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ✓ 5 ₩ D		9. OGRID Number
2. Name of Operator		227588/
Range Operating New Mexico, Inc. 3. Address of Operator		10. Pool name or Wildcat
100 Throckmorton St., Ste. 1200, Fort Worth, TX 76102		San Andres SWD
4. Well Location		
Unit Letter G: 2310 feet from the north line and 1980 feet from the east line		
Section 5 Township 22S Range 37E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3424 GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box	to Indicate Nature of Notice,	, Report of Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON 🖾 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS. 🔲 PANDA L		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE	Ì	
	☐ OTHER:	
The Reviewed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
Propose to release packer @ 4,761'. TIH and re-set packer at 4,990'. Cut 2 3/8" tubing at 4,870' and TOOH. RIH with		
wireline and set CIBP @ 4850'. Dump 2sx cement on top. Pressure test casing to 300 psi. If casing does not pressure test wireline and set CIBP @ 4850'.		
to 300 psi pick up plug and packer combination and commence isolating leak."		
500±		
000		
,		
Condition of Approval: Notify OCD Hobbs		otify OCD Hobbs
office 24 hours prior to running MIT Test & Chart		
Spud Date: 3-19-1967	Rig Release Date:	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
	•	
SIGNATURE LENGTH	TITLE Sr. Reg. Sp.	DATE <u>1-27-2009</u>
	n 11 11	. Orocourage com DUONE.
Type or print name Paula Hale	E-mail address: _phale@rang	
For State Use Only ANS 0 2009		
APPROVED BY: TITLE DISTRICT 1 SUPERVISOR DATE		
Conditions of Approval (if any):		