Subtitit 3 Copies To Appropriate District State of New Mexico	Form C-103
Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr , Hobbs 200 1834	WELL API NO. 30-025-20651
Subtrict 3 Copies To Appropriate District Office District 1 1625 N French Dr., Hobbs 2016 District 11 1301 W Grand Ave, Artesia; NM 3610 3 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE 🔀 💆
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM 87505	
	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	/ 'r.
PROPOSALS)	Boyz Fee
1. Type of Well: Oil Well Gas Well Other	8. Well Number 3
2. Name of Operator Mack Energy Corporation ✓	9. OGRID Number 13837
3. Address of Operator	I 0. Pool name or Wildcat
P. O. Box 960 Artesia, NM 88211-0960	Arkansas Junction; San Andres
4. Well Location	J
Unit Letter F 1980 feet from the North line and 1980 feet from the West line	
Section 30 Township 18S Range 37E NMPM County Lea	
I 1. Elevation (Show whether DR, RKB, RT, GR, etc.	
3750' GR Pit or Below-grade Tank Application or Closure	
Pit typeDepth GroundwaterDistance from nearest fresh water wellDistance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	ILLING OPNS PAND A D
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB
Compl	etion
OTHER: OTHER. OTHER. Completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
Notify OCD 24 hours prior to starting plugging operations	
1) Set CIBP @ 4550' w/35' cmt cap.	• • •
2) Set 50sx cmt plug from 3250' to 2750'. Cover 8 5/8 shoe and base of salt'.	
3) Set 25sx cmt plug from 1625' to 1375'. Spot 25 5x plug at 405 (Sur	face shoe)
5) Install P & A Marker INSTALL STEEL PLATE 4-H below ground level. GPS in & CALL FOR INSPECTION PRIOR TO COVERING HOLE	
Note: Circ. well with salt gel mud consisting of at least 9.5# Brine with 25 pounds	
of gel per barrel after the bottom plug is set.	
The Oil Conse	vation Division Must be notified
24 nours prior	to the beginning of plugging operations
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE Level Shevell TITLE Production Clerk DATE 12/30/09	
Type or print name Jerry W. Sherrell E-mail address: jerrys@macke	energycorp.com Telephone No. (575)748-1288
For State Use Oply	
APPROVED BY: Wash Whitaken TITLE Compliance	2 Oficer DATE 1/28/2010
Conditions of Approval (if any):	DATE 11. TO 10

Mack Energy Corporation

Boyz Fee #3 Sec. 30 T18S R37E 30-025-20651

