

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name Dessie Sawyer
3. Address of Operator P. O. Box 1861 - Midland, TX	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE A <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>9 S</u> RANGE <u>36 E</u> NMPM.	10. Field and Pool, or Whichever Crossroads Devonian
11. Elevation (Show whether DF, RT, GR, etc.) 4039 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-21-80 MIRU. RAN 2 7/8 TBG TAGGED FILL 5655'.
12-22-80 DISP HOLE W/125 BBLs MUD, POH W/2 7/8 TBG. DUG OUT CELLAR, OPEN BH 2 HRS FLOW 17 BO, NO WTR SLIGHT GAS. LOON.
12-23-80 PERF 5 1/2 CSG @ 4600'. CIRC OUT 190 BBLs FROM BEHIND CSG.
12-24-80 REMOVE WELLHEAD, WELD ONTO 5 1/2 CSG W/LIFT NIPPLE, WORKED PIPE, CSG. PARTED PULLED 40 JTS.
12-25- & 26-80 CREW OFF
12-27-80 PULLED TOTAL 177 JTS. 5 1/2 CSG. INSTALL WH & BOP.
12-28-80 RAN 2 7/8 TBG TO 5788 TOP CSG STUB, SPOT 100 SX CLASS C CMT @ 5788. LWR & TAG PLUG 5768, SPOT ADDITIONAL 100 SX "C" CMT 5768-5650; RAISE TS 5000'.
12-30-80 LWR TBG, TAG CMT PLUG 5498. RAISE TS 4900 SPOT 35 SX CMT PLUG 4900-4800. RAISE TS 4650 SPOT 100 SX CMT PLUG @ 4650. LWR & TAG PLUG 4424. RAISE TS 2335.
12-31-80 SPOT 35 SX CMT PLUG 2335-2235. POH W/TBG. REMOVE BOP & WH, SPOT 10 SX CMT PLUG @ SURFACE. WELD STEEL PLATE ON 9 5/8 CSG INSTALL MARKER. RR & CLEAN LOCATION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Doris Williams TITLE Sr. Accounting Assistant DATE 1-23-81

APPROVED BY Eddie Seay TITLE OIL & GAS INSPECTOR DATE FEB 1 1982

CONDITIONS OF APPROVAL, IF ANY: