

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 18 11 36 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sunray DX 011 Company		8. Farm or Lease Name Dessie Sawyer
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 9-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Crossroads Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4039 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug Back and Temporarily Abandon

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up and ran tubing w/RTTS pkr. to 5746'. Could not get below. Pulled out of hole and left safety joint and packer in hole. Tried to fish packer, could not retrieve.
2. Ran tar impression block. Showed packer leaning over. Casing parted. Attempted to dress off fish and pull. Unable to retrieve fish.
3. Pumped in 60 BW, well on vacuum. Mixed and pumped in 200 sxs Trinity Inferno Cmt. After 20 bbls. displacement, cement broke and circulated water out of Bradenhead. Shut Bradenhead. SI over night.
4. Pump in break in casing @ 5746'. Broke circ. around Bradenhead. Shut Bradenhead. Mixed 200 sxs Incore Poz and displaced past 5746' w/2 BW. SI @ 1400#. WOC 5 hrs. Open Bradenhead. Pressured 5-1/2" csg. to 2000#. Held OK. Move rig off (5-25-68).
5. Well plugged back to 5746'. Now TA pending further evaluation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings TITLE District Engineer DATE June 17, 1968

APPROVED BY John W. Puryear TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: