

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: SANTA FE PACIFIC "SUDDIN" Well No. B-1

Field: CROSSROADS

County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. MOVE IN CASING PULLING LIMIT & PULL 3" TBS
2. RUN 2" TUBING & SPOT 35' IN PLUG OVER
PERFORATED INTERVAL (9697'-9875')
3. CIRCULATE HOLE TO MWD LADEN FLUID
4. DETERMINE FREE POINT OF 7" Csg. CUT
OFF Csg. & PULL (5000')
5. SPOT 25 SN CEMENT PLUG ACROSS CUTOFF POINT
6. SPOT 10 SN CEMENT PLUG @ SURFACE
7. CUT OFF WELL HEAD, AND INSTALL MARKER