

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-03627
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name CROSSROADS SILUR (formerly U D Sawyer #1)
8. Well No. 1
9. Pool name or Wildcat DEVONIAN SWD
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4043' Gr

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W. Wall, Suite 1900
Midland, TX 79701

4. Well Location
Unit Letter A : 660 feet from the North line and 660 feet from the East line
Section 33 Township 9S Range 36E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒	REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOBS ☐
OTHER: ☐	OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

NU BOP & RIH w/5-1/2" CICR & tbg, pump thru & set @ 2100'.
Sqz 1265 sx cmt under retainer 12,700' - 2100', overdisplace & WOC.
Pressure test under retainer, cap retainer w/25 sx from 2100' - 2000'
Pull tbg to 325', spot 25 sx cmt, WOC & tag 325' - 225'
Pull tbg to 60', spot 10 sx from 60' - 3'. Install marker

See unsuccessful attempt to recover fish 4/97 report on back of form

Well History- 13-3/8" csg @ 275' w/325 sx, circ
9-5/8" @ 4602 w/3500 sx
5-1/2" Baker Model N pkr @ 4475' (ID of pkr milled)
5-1/2" 17 & 15# N80 & J55 csg @ 12,700' w/1250 sx - cmt circ (7-7/8" hole).
Devonian Open hole zone 12,700' - 13,120'. TD 13,120'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 07/16/2002

Type or print name Bonnie Husband Telephone No. (915)684-4293

(This space for State use) ORIGINAL SIGNED BY GARY W. WINK DATE JUL 25 2002
APPROVED BY OC TITLE REPRESENTATIVE II/STAFF MANAGER DATE _____

Conditions of approval, if any:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

Saga Petroleum
Daily Workover Report
U.D. Sawyer SWD #1

4/18/97 MIRU Unit 6011. SD for weekend.

4/21/97 MIRU Weatherford. RU KTS Pmp Truck. Pumped 375 bbls PW, kill well. NDWH. Pulled & LD 5 jts 4-1/2" csg. Tong broke dn. SDFN.

4/22/97 MIRU Weatherford. MIRU KTS Pmp Truck. Pumped 300 bbls PW & kill well. Pulled & LD 28 jts 4-1/2" csg + 24' parted jt. RD Weatherford. NU BOP. MI Star Tool. PU 6-3/4" overshot. MI & unload 2-7/8" tbg from Eagle Pipe. PU 69 jts, tag up @ 2177'. Top of fish should have been @ 1362'. Pulled over shot out of hole. SDFN.

4/23/97 PU overshot 6-3/8", tag up @ 2177'. Pulled tools out of hole, LD overshot. PU 6-3/4" bit & bit sub. Tag up @ 2177'. Worked for 2-1/2 hrs, would not go. RU KTS Pmp Truck. Pmpd 90 bbls PW. Worked dn to 2166'. Pulled bit & bit sub out of hole. LD tools. Ran tbg w/ 2-7/8" tbg collar on btm. Tag up @ 2182'. PU & hung up 2180'. Turn pipe came lose. Pulled tbg out of hole. Cas claps & parted. SDFN.

4/24/97 PU 6-1/2 Lead block. Tag up @ 2172'. Pulled & LD lead block. Csg collapsed. Waited on tools. PU 3-13/16" swedged bumper sub jars, 6 DC 4-3/4". TTH. Tag up @ 2185'. Worked dn to 2209'. Lose Swedge. Pulled tools out of hole. Broke pin off x-over. LD tools. SDFN.

4/25/97 PU overshot 4-5/8". Tag up @ 2176'. Worked up & down turn pipe to right, could not fish collar. POOH w/ tools. LD overshot. SDFN.

4/26/97 Open well up. PU one jt 2-7/8" tbg. Bent jt. PU tapier tap. TTH & Tag up @ 2179'. Worked tool up & dn. Could not fish DC. Pulled tool out of hole. Bent tub more, ran tools in hole to 2179', could not fish. SDFN.

4/27/97 Open well up. LD tub, DC & tools. ND BOP. NUWH. Evaluating for P&A.