

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-03629
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name CROSSROADS SILUR DEVONIAN UNIT	
8. Well No.	101
9. Pool name or Wildcat CROSSROADS SILUR DEV	

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. Type of Well: <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> OtherSWD	
2. Name of Operator Saga Petroleum LLC	
3. Address of Operator 415 W. Wall, Suite 1900 Midland, TX 79701	
4. Well Location Unit Letter A : 660 feet from the N line and 660 feet from the E line Section 34 Township 9S Range 36E NMPM County LEA	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p>		<p>SUBSEQUENT REPORT OF:</p>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: MIT - TA <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

Inspection No. iBEP0208151601 - Failed MIT 3-22-02
11-14-02 NDWH, RIH w/5-1/2" HDR pkr on 2-3/8" tbg to 4090', set pkr, NUWH.
11-15 RU kill trk, load tbg w/40 bbls, attempt to test to 500 psi, will not test, load & attempt to test annulus above pkr, Blow WH apart. SD & WO WH parts
11-18 Release pkr, POOH w/tbg & pkr, LD pkr, RIH to 2500', circ hole w/225 BFW, POOH w/tbg, cut off WH, weld on new flanged WH. NUBOP, Load & test well for MIT, will not test. SIH w/pkr.
11-19-22 Continue to TIH w/tbg to 6706', set pkr, attempt to test, pkr does not have enough weight on it to hold good, POOH, PU tension pkr, TIH to 6700, retest 5-1/2". Release pkr, test csg up every 5 stds, find top of leak @ 4697', csg test good above 4697' & good below 7397'. Rels pkr, RIH w/tbg, POOH, LD rental tbg & pkr, RIH open-ended to 4740', break circ, spot 14 bbls Maraseal, PU to 4240', reverse 20 bbls up tbg, pump 6 bbls away, SI w/800 psi on well. SITP vac 1 min, open BOP. POOH LD all tbg. ND BOP install WH flange
11-28 Pressure up to 500 psi - held for 30 mins - good test - Chart attached

This Approval of Temporary Abandonment Expires 12/12/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 12/10/2002

Type or print name Bonnie Husband Telephone No. (915)684-4293
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

