NO. OF COPIES RECEIVED	7		Form C-103
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION		Supersedes Old
SANTAFE			C-102 and C-103 Effective 1-1-65
FILE		STOPEN PATION COMMISSION	PHACHAG 1-1-02
U.S.G.S.	-		Sa. Indicate Type of Leane
LAND OFFICE	-		State . Fre. [X]
OPERATOR	-		5, State Oil & Gas Lease No.
	I ·		Fee
SHMD	RY NOTICES AND REPORTS	ON WELLS	mmmmmm.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOP PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
1.			7, Unit Agraement Name
OIL WELL OTHER.			None
2. Name of Operator			8, I'arm or Loane Name
TEXACO :Inc.			U. D. Sawyer
3. Address of Operator			9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240			3
4. Location of Well			10. Field and Pool, or Wildcat
I	2310 FEET FROM THE	South 990	Crossroads Devonian
UNIT LETTER	FEET FROM THE	LINE AND FEET FRO	mmmmmm.
East	10N 34 TOWNSHIP 9	-S 36-E	
THELINE, SECT	TOWNSHIP	RANGE NMPA	~ <i>() </i>
	15. Elevation (Show whe	ther DF, RT, GR, etc.)	12. County
		030' (D. F.)	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
[]			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	MEMEDIAL WONK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1703.			
THE FOLLOWING WORK HAS BEEN COMPLETED ON SUBJECT WELL:			
1. Pulled production Tubing and Packer.			
2. Ran tubing w/packer and set @ 12,095.			
S Without and out of any of the second secon			
3. Acidized open hole 12,164' - 12,172' W/2500 gals. 28% Super X Acid, followed			
W/1250 gals. 5% acid, 2 gals. LST, and 150# Unibeads.			
, , , , , ,	, _ g,,		
4. Re-Acidized W/2500 Gals. 28% Super X Acid, 1250 gals. 5% Acid, 2 gals. LST and			
flushed W/52 Bbls. Water.			
5. Swab, Install Hyd PE, Test, and return to production.			
· · · · · · · · · · · · · · · · · · ·			

Assistant District
SIGNED TITLE Superintendent

Approved by CONDITIONS OF APPROVAL, IF ANY: