

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HUBB'S OFFICE D. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 JUN 2 10 39 AM '69

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2942
7. Unit Agreement Name
8. Farm or Lease Name Pray SWD
9. Well No. 2
10. Field and Pool, or Wildcat -
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- SWD

2. Name of Operator
BTA Oil Producers

3. Address of Operator
104 So. Pecos, Midland, Texas 79701

4. Location of Well
 UNIT LETTER C, 660 FEET FROM THE North LINE AND 1980 FEET FROM
 THE West LINE, SECTION 5, TOWNSHIP 10-S RANGE 36-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4042' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Re-entry <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-9-69: Cleaned out cellar. Pick up 12½" bit. Drilled on junk, to 1325', top 8-5/8" @ 1325'. Circ. hole clean.

5-12-69: Wash through bridge @ 1950'. Drilled on junk and cement plugs 3811-4026', 4860-5920'. Now circ. @ 7636' to condition mud.

5-14-69: Drl. bridge @ 9300'. Drilled and washed to 9900'. Circ. hole 5½ hrs., went to drilling and washing from 9900' to 10,600' -still washing.

5-15-69: Washed to 12,154'. Circ. hole. Prep to run casing.

5-16-69: Ran 5½" O.D. 17 & 20# J-55 casing set @ 12,145' w/300 sx cement. Plug down 3 a.m. 5-16-69. WOC. After WOC 18 hrs., pressure tested casing to 1500# for 30 min. Held O.K.

5-19-69: Now drilling 4-5/8" hole @ 12,225'.

5-23-69: Drilled 4-5/8" hole to 12,502'. T.D.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Drilling Manager DATE 5-28-69

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: