							-				
			NEW MEXI						И		FORM C-10 (Rev 3-55)
			MISCEI	LLANEO	OUS R	EPOR	TS ON	WELLS			
		(Su	bmit to approp	oriate Dist	rict Off			<u>_</u>			
Name of Compa	<sup>any</sup> Max P	ray							l Bldg.,	Okla.	City 2, C
Lease	State E			Well No. <b>2</b>		Letter C	Section 5	Township 10	South	Range 3	6 East
ate Work Perf	formed 23, 1961	P	ool Unde	signated	4		(	County Lea	L		
				S A REPOR		(Cbeck d	appropria				
Beginning	g Drilling Oper	rations	C	asing Test	and Cem	nent ]ob	[	Other (E	xplain):		
Plugging			R	emedial Wo	rk						
etailed accou	int of work don	ne, natu	ire and quantity	of materia	ls used,	and resi	ilts obtai	ined.	······		
	vy drillir	ng mi	id was lef	t in wel	1 hetu		1	NT		nulled	Verhal
		nis di	ryhole in t ore pluggi	the fore	going	manr					
February		nis di befo	ryhole in t ore pluggi	the fore ng was	going begun	manr 1.	her wa	Company		lephon	e on
February	7 21, 1961,	nis di befo	ryhole in t ore pluggi	Positio	going begun <sup>2n</sup> Tool	manr h- pushe DIAL W	r ORK RE	Company Sha	ed by te rp Drilli	lephon	e on
February Witnessed by	7 21, 1961, Raymond	his di befo Ran	ryhole in t ore pluggi dolph	Positio	going begun <sup>on</sup> Tool R REME IGINAL	manr h. pushe	r ORK RE	Company Sha	rp Drilli	ng Co	e on
February Witnessed by DF Elev. 40	7 21, 1961, Raymond	nis di befo Ran	ryhole in t ore pluggi dolph FILL IN BE	Positio	going begun <sup>on</sup> Tool R REME IGINAL	manr pushe DIAL W WELL D	r ORK RE	Company Sha PORTS 01 Producing	rp Drilli NLY Interval	ng Co	e on mpany
February Witnessed by OF Elev. 40 Fubing Diamet	7 21, 1961, Raymond 054	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164	Positio	going begun <sup>on</sup> Tool R REME IGINAL	manr pushe DIAL W WELL D	r ORK RE	Company Sha PORTS 01 Producing	rp Drilli NLY Interval	ng Con	e on mpany
February Witnessed by DFElev. 40 Fubing Diamet Perforated Inte	Raymond	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164	Positio	going begun <sup>on</sup> Tool R REME IGINAL	manr h- DIAL W WELL D Oil Strin	r ORK RE	Company Sha E PORTS 01 Producing	rp Drilli NLY Interval	ng Con	e on mpany
February Witnessed by DFElev. 40 Fubing Diamet Perforated Inte	Raymond	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164	Positio	going begun <sup>Dn</sup> Tool R REME IGINAL TD	manr h- DIAL W WELL D Oil Strin	r ORK RE DATA ng Diame	Company Sha E PORTS 01 Producing	rp Drilli NLY Interval	ng Con	e on mpany
February Witnessed by	Raymond	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164	Positio Positio LOW FOR PB RESU	going begun <sup>Dn</sup> Tool R REME IGINAL TD	manr pushe DIAL W WELL D Oil Strin Produci F WORK ction	r ORK RE ATA ng Diame ng Forma (OVER Water F	Company Sha E PORTS 01 Producing	rp Drilli NLY Interval	Iephon ng Con ing Depth	e on mpany
February Vitnessed by DFElev. 40 Fubing Diamet Perforated Inte Open Hole Inte	<b>21, 1961,</b> Raymond <b>054</b> ter   erval(s)   erval   Date of	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti	Positio Positio LOW FOR PB RESU	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORK ction	r ORK RE ATA ng Diame ng Forma (OVER Water F	Company Sna E PORTS 02 Producing eter ation(s)	rp Drilli NLY Interval Oil Str	Iephon ng Con ing Depth	e on mpany mpletion Date
February Witnessed by DF Elev. 40 Fubing Diamet Perforated Inte Dpen Hole Inte Test Before	<b>21, 1961,</b> Raymond <b>054</b> ter   erval(s)   erval   Date of	nis di befo Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti	Positio Positio LOW FOR PB RESU	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORK ction	r ORK RE ATA ng Diame ng Forma (OVER Water F	Company Sna E PORTS 02 Producing eter ation(s)	rp Drilli NLY Interval Oil Str	Iephon ng Con ing Depth	e on mpany mpletion Date
February Vitnessed by DF Elev. 40 Fubing Diamet Perforated Inte Dpen Hole Inte Test Before Workover After	Raymond Raymond 054 ter erval Date of Test	nis di befo l Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti	Position Position ELOW FOR PB PB RESU on Ga	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORK ction D	r ORK RE ORK RE DATA ng Diame ng Forma KOVER Water F B	Company Sha E PORTS 01 Producing etter ation(s) Production 3 P D	rp Drilli NLY Interval Oil Str Cubic feet	ephon ng Con ing Depth	e on mpany mpletion Date
February Witnessed by DF Elev. 40 Tubing Diamet Perforated Inte Open Hole Inte Test Before Workover After	Raymond Raymond 054 ter erval Date of Test	nis di befo l Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti BPD	Position Position ELOW FOR PB PB RESU on Ga	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORK ction D	r ORK RE ORK RE DATA ng Diame ng Forma KOVER Water F B	Company Sha E PORTS 01 Producing eter ation(s) Production B P D fy that the in my knowled	rp Drilli VLY Interval Oil Str GOF Cubic feet	ren above	e on mpany apletion Date Gas Well Poten MCFPD
February Witnessed by DF Elev. 40 Fubing Diamet Perforated Inte Dpen Hole Inte Test Before Workover After Workover	Raymond Raymond 054 ter erval Date of Test	nis di befo l Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti BPD	Position Position ELOW FOR PB PB RESU on Ga	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORH ction D I here to the	r ORK RE ORK RE DATA ng Diame ng Forma (OVER Water F B Solution Solution B Solution B Solution Solution B Solution Solut	Company Sha E PORTS 02 Producing eter ation(s) Production B P D fy that the in my knowled	rp Drilli NLY Interval Oil Str Cubic feet	ren above	e on mpany apletion Date Gas Well Poten MCFPD
February Vitnessed by FElev. 40 Fubing Diamet Perforated Inte Perforated Inte Den Hole Inte Test Before Workover After Workover	Raymond Raymond 054 ter erval Date of Test	nis di befo l Ran	ryhole in to ore pluggi dolph FILL IN BE 12, 164 Tubing Depth Oil Producti BPD	Position Position ELOW FOR PB PB RESU on Ga	going begun <sup>2n</sup> Tool R REME IGINAL TD JLTS O	manr pushe DIAL W WELL D Oil Strin Produci F WORH Ction D I here to the Name	r ORK RE ORK RE DATA ng Diame ng Forma (OVER Water F B S Sovertifies best of On	Company Sha E PORTS 01 Producing eter ation(s) Production B P D fy that the in my knowled	rp Drilli NLY Interval Oil Str Cubic feet	ren above	e on mpany apletion Date Gas Well Poten MCFPD