

N. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE **APPLICATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER _____	7. Unit Agreement Name
2. Name of Operator Tom L. Ingram	8. Farm or Lease Name Dickinson
3. Address of Operator P. O. Box 1757, Roswell, NM 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>west</u> LINE, SECTION <u>33</u> TOWNSHIP <u>10-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Undesig. Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4008 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER _____ <input type="checkbox"/>	OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-21-84 Plan to Plug and Abandon as follows:

- CIBP & 30' cmt @ 11,200
- 100' cmt plug @ 7700-7800 (Top of ABO)
- 100' cmt plug @ 4950-5050 (inside & outside 5 1/2 csg stub)
- 100' cmt plug @ 2150-2250 (Top of salt)
- 10 sx cmt plug @ Surface and place dry hole marker.
- Mud laden brine will be between plugs.

Verbal permission obtained for this plugging from Jerry Sexton on 12/21/84

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joseph L. Ingram TITLE Engineer DATE 12/21/84

APPROVED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE DEC 27 1984

CONDITIONS OF APPROVAL, IF ANY: