

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tom L. Ingram	8. Farm or Lease Name Cryer
3. Address of Operator POB 1757, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>34</u> TOWNSHIP <u>10S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Dickinson-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4015 KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval obtained from John Runyan on 10/11/73 to P & A as follows:
Cut 2-3/8" tubing above packer & pull. Placed 100' plug @ tubing stub. 100' plug @ 7767.
100' plug @ 5670. 100' plug @ stub of 5 1/2" casing. 100' plug @ base of 8-5/8"(4227).
100' plug @ base of salt. 100' plug top of salt. 100' plug @ stub of 8-5/8". 100' plug
@ base of surface (345'). 10 sack plug @ surface. Set marker and clean location. Mud
laden brine to be placed between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Tom L. Ingram</u>	TITLE <u>Operator</u>	DATE <u>10/16/73</u>
Orig. Signed by Joe D. Ramey Dist. I, Supv.		
APPROVED BY _____	TITLE _____	DATE <u>OCT 18 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		