

ED		
↓		
E		

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 31 3 40 PM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2373	
7. Unit Agreement Name	
8. Farm or Lease Name Phillips State	
9. Well No. 1	
10. Field and Pool, or Wildcat Cindy (Wolfcamp)	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

L ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Meadco Properties, Ltd.

Address of Operator

606 Vaughn Building, Midland, Texas

Location of Well

UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM

THE West LINE, SECTION 22 TOWNSHIP 11S RANGE 36E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

4008' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Run tubing open ended to 10,000 feet and spot 20 sacks cement plug to 9800 feet. Displace the cement with mud laden fluid. Work to commence 7-31-69.
- Pull tubing
- Shoot 4 1/2" casing at 8900 feet and if free, spot 25 sack plug at casing stub. If not free, shoot at 8700 and/or 8500'. Displace the cement with mud laden fluid.
- Pull casing to 7900' and spot 25 sack plug to 7800' or above above at 7905'. Displace the cement w/mud laden fluid.
- Pull casing to 5780' and spot 25 sack plug to 5680' or above Glorieta at 5780'. Displace the cement w/mud laden fluid.
- Pull casing to 4425' and spot 25 sack plug to 4300'. This will be 50' below 9 5/8" Intermediate casing at 4375'
- Pull casing
- Run one joint of tubing to 30' and spot 10 sack plug in top of 9 5/8" casing.
- Erect permanent marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Clayton D. Roach

TITLE Agent

DATE 7-31-69

APPROVED BY John W. Runyan

TITLE Geologist

DATE JUL 31 1969

CONDITIONS OF APPROVAL, IF ANY: