

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company		8. Farm or Lease Name ODC "C"
3. Address of Operator P. O. Box 1659 Midland, Texas		9. Well No. 2
4. Location of Well UNIT LETTER L 660 FEET FROM THE West LINE AND 1930 FEET FROM South LINE, SECTION 4 TOWNSHIP 9-3 RANGE 37-E N.M.P.M.		10. Field and Pool, or Wildcat Allison Pennsylvanian
11. Elevation (Show whether DF, RT, GR, etc.) 4024 GR		12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be loaded with 10 # mud. The pay zone 9636 - 9656 will be covered by a 25 sack plug of cement up to 9500'. We will cut and pull some 6000' of 4 1/2". A 25 sack plug will be placed 50' inside this stub. 25 sacks will be placed @ 5500', 25 sacks at 4166' (shoe of the 7 5/8). The 7 5/8 will be cut and pulled @ 600' and 25 sacks placed in this stub. 25 sacks @ 305' (shoe of 10 3/4) with 10 sacks at the surface.

A cleanup and marker will be placed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. H. Crews* **O. H. Crews** TITLE Administrative Coordinator DATE June 2, 1965

APPROVED BY *[Signature]* TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: