

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <b>Great Western Drilling Company</b>		8. Form or Lease Name <b>ODC "B"</b>
3. Address of Operator <b>P. O. Box 1659 Midland, Texas</b>		9. Well No. <b>1</b>
4. Location of Well CORNER <b>J</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1780</b> FEET FROM <b>East</b> LINE, SECTION <b>5</b> TOWNSHIP <b>9-S</b> RANGE <b>37-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Allison Pennsylvanian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4032 GR</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 PULL OR ALTER CASING ☐  
 OTHER ☐

PLUG AND ABANDON ☒  
 CHANGE PLANS ☐  
 OTHER ☐

REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER ☐

ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be loaded with 10 # mud. The pay zone 9647 - 9670 will be covered 100' by a 25 sack cement plug. Some 6000' of 4 1/2" will be pulled and a 25 sack plug set in the stub, 25 sacks will be spotted @ 5500', 25 sacks in the shoe of the 7 5/8" @ 4296. The 7 5/8 will be pulled @ 600' with 25 sacks in the stub. 25 sacks @ 257' (shoe of 10 3/4) and 10 sacks at the surface.

A cleanup and marker will be made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews TITLE Administrative Coordinator DATE June 2, 1965

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: