Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240

CONDITIONS APPROVAL, IF ANY:

1625 N. French Dr., Hobbs, NM 88240	2040 S. Pacheco		WELL API NO.
<u>DISTRICT II</u> 811 S. First, Artesia, NM 88210	Santa Fe, New Mexico 87505		30-025-04991
DISTRICT III			5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410			STATE X FEE
<u>DISTRICT.IV</u> 2040 South Pacheco, Santa Fe, NM 8750	5		6. State Oil & Gas Lease No.
	AMENDED		
	AMENDED		LG-6801
	SUNDRY NOTICES AND REPORTS	ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFE	RENT RESERVOIR USE "APPLICAT (FORM C-101) FOR SUCH PROPO		
I. Type of Well:	(I OKIN C-101) I OK SOCIT PROFE	oaco,	
OIL X WELL	GAS OTHER		Morse
2. Name of Operator	WELL OTHER		8. Well No.
C. W. Trainer			1
3. Address of Operator c/o OIL REPORTS & GA	AS SERVICES, INC.,1008 W. BROAD	VAY. HOBBS. NM 88240	9. Pool name or wildcat N. Echols Devonian
4. Well Location			
Unit Letter E :	1980 Feet From The NORTH	Line and 660	Feet From The WEST Line
Om Little	raction the trotter	Ente and	rectribilitie VVLO1
Section 27 Township	10S Range 37E		NMPM LEA County
	10, Elevation (Show whether DF, RKB, RT, GR, ect 3937' GR	.)	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK			
PERFORM REMEDIAL WORK	X PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	. PLUG & ABANDONMENT
PULL OR ALTER CASING CASING TEST & CEMENT JOB			
OTHER: To amend 3/8/00 sund	ry	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
OKONO MIDILI III. III. III. III. III. III. III.			
2/12/00 MIRU pulling unit. Unflange wellhead & NU BOP. Release pkr. POH w/2 7/8" tbg. 2/17/00 DO from 11,636'-11,672'. Circ. hole clean.			
2/18/00 Tag fish 11,676'. POH w/tbg. Go in hole w/84 stands.			
2/19/00 Wash over fish. Circ. hole clean			
2/21/00 Tag top of fish @ 11,672'. Wash down to 11,742'. Recovered fish.			
2/22/00 Tag @ 11,742'. Circ. hole clean. 2/23/00 POH w/tbg. Tag top of 5 1/2" @ 3850'. Set wireline pkr @ 11,690' & tag.			
2/24/00 TIH w/Model "R" pkr & set @ 4050'. Pressure csg to 300# & bleed off. Apparent hole in 8 5/8" or around 5.5" csg. POH w/pkr. TIH with			
dip tbg assembly below seal assembly w/2 1/16" tbg + 100 jts.			
2/25/00 POH w/tbg. Stung 2 7/8" "Scab" protective liner into wireline pkr @ 11,690' w/hook wall pkr @ 4004'. Test csg to 500# w/no leakoff.			
POH, LD pkr. RIH w/on/off tool, seating nipple & 372 jts 2 7/8" L80 8rd tbg. Load & test csg to 500# OK. ND BOP & flange up wellhead. 2/28/00-3/3/00 RIH w/gas anchor, sucker rods, polish rod & pump. Clean off location & set pumping unit.			
3/7/00 Put back on prod. Test 16-17 hrs 20 BO, 90 BW.			
0, 0			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Han i	Me - a	-	/
SIGNATURE	TITLE_	AGENT	DATE 03/08/2000
TYPE OR PRINT NAME Gaye	feard		TELEPHONE NO. (505) 393-2727
(THIS SPACE FOR STATE USE)		* 	
APPROVED BY	TITLE		DATE
			DATE