

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-6868

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name	
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State E "B"	
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 1	
4. Location of Well UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>10-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat N. Echols, Dev.	
15. Elevation (Show whether DF, RT, GR, etc.) 3949' DF	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>		
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>		
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 2-3/8" tubing and set in Baker packer at 5300'. Spotted 50 sx. cement plug in 5-1/2" casing from 11,225' to 11,669'. Cut and pulled 4482' 5-1/2" OD casing. Spotted 50 sx. cement plug in and out top of 5-1/2" casing from 4692' to 4270'. Spotted 30 sx. cement plug in 8-5/8" casing and 11" o en hole from 4240' to 4300'. Cut and pulled 1002' 8-5/8" casing. Spotted 30 sx. cement plug from 975' to 1030' and 35 sx. cement plug from 320' to 365'. Spotted 10 sx. cement plug at surface with dry hole marker. Well P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Area Superintendent</u>	DATE <u>12-31-73</u>
APPROVED BY <u>[Signature]</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		