

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFF CE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1516
7. Unit Agreement Name
8. Farm or Lease Name New Mexico 'AR' St.
9. Well No. 1
10. Field and Pool, or Wildcat Echols (Devonian)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXACO Inc.
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER E / 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 11-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3957' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran cement retainer in 5½" casing & set @ 11,290'.
2. Displace hole w/mud & squeezed perforations 11,428-11,473' w/ 100 sx. cement.
3. Shot 5½" casing off @ 4521' & pulled 4520'.
4. Spotted 45 sx. cement plug @ 4520-4300'.
Spotted 45 sx. cement plug @ 4200-4150'.
Spotted 45 sx. cement plug @ 1800-1740'.
Spotted 10 sx. cement plug @ surface.
5. Installed dry hole marker & clean location 4-10-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John W. Runyan* TITLE Asst. Dist. Supt. DATE 4-24-73
APPROVED BY *John W. Runyan* TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: