

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION  
P.O. BOX 1980  
HOBBS, NEW MEXICO 88240

Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
TOCO, L.L.C.

3. Address and Telephone No.  
P.O. Box 888, Hobbs, NM 88241 505-392-7050

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Unit Letter L, 1980' FSL & 660' FWL  
Section 7, T-9S, R-38E

5. Lease Designation and Serial No.

NM-83628

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sawyer Federal #1

9. API Well No.

30-025-07054

10. Field and Pool, or Exploratory Area

Sawyer Devonian

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION


- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 4/28/93 1. Set CIBP @ 4950' and cap w/35 sx cement.  
2. Spot cement plug 3922-4287' w/35 sx cement.  
3. Spot cement plug 1435-1800' w/35 sx cement.  
4. Spot cement plug 225-475' w/25 sx cement.  
5. Spot cement plug 0-62' w/7 sx cement.  
6. Cut off wellhead and install dry-hole marker  
Restore location.



Approved as to plugging of the well down.  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed Sharon M. Kelley

Title Agent

Date 2/10/95

(This space for Federal or State office use)

Approved by Signed by Shannon J Shaw

Title PETROLEUM ENGINEER

Date 3/20/95

Conditions of approval, if any: