

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. L. C. 060909	
2. NAME OF OPERATOR Ralph S. Cooley		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 254, Midland, Texas		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 feet from South Line and 660 feet from West Line, Section 18, Township 9 South, Range 38 East		8. FARM OR LEASE NAME Brown "09"	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3964 GR		10. FIELD AND POOL, OR WILDCAT Sawyer San Andres Gas	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T9S, R38E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spotted through tubing cement plug 4850' inside 5-1/2" casing to total depth 4982'.
2. Loaded hole with 11.5 pound 60 viscosity mud.
3. Shot off 5-1/2" casing 1250 feet. Pulled 14 joints of 5-1/2" casing, total 1250 feet.
4. Spotted cement plug with tubing 1200' to 1350' across stub of 5-1/2" casing.
5. Spotted cement plug of 100 feet with tubing across casing seat of 10-3/4" surface casing.
6. Spotted 50 foot cement plug in the top of the 10-3/4" surface casing.
7. Erected regulation marker.
8. Cleaned location, filled burn pit. Graded location. Ready for inspection.

18. I hereby certify that the foregoing is true and correct.

SIGNED *Ralph S. Cooley* TITLE Operator DATE February 4, 1966

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED

JUN 1 1966

J. L. GORDON
ACTING DISTRICT ENGINEER

XERO COPY

XERO COPY

XERO COPY

XERO COPY