	ARIMENI UP THE INT	ERIOR (Yother instructions	OR FC- 5. LEASE DESIGNATION AND SERIAL NO
GEOLOGICAL SURVEY			L.C. 065151
	NOTICES AND REPORT	B ON DAVELLS	6. IF INDIAN, ALLOTTRE OR TRIBE NAM
	proposals to drill or to deepen or p PPLICATION FOR PERMIT—" for s		
Use "Al	PPLICATION FOR PERMIT—" for s	uch proposals.)	7. UNIT AGREEMENT NAME
OIL GAS	'H ER		
2. NAME OF OPERATOR		· · · · · · · · · · · · · · · · · · ·	8. FARM OR LEASE NAME
Ralph S. Cool	ey		Brown "51"
3. ADDRESS OF OPERATOR			9. WELL NO.
P. O. Box 254. Midland. Texas 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT
At surface 660 feet from North Line, 585 feet from West Line			Saurran San Andrea C
660 ieet ir	•		11. SEC., T., R., M., OR BLK. AND
Section 19,	Township 9 South, Ra	ange 38 East	SURVEY OF AREA 19 - T95 - R38E
14	1 18 90 000 001 001 001		
14. PERMIT NO.	15. ELEVATIONS (Show whet) 3967 GR		12. COUNTY OF PARISH 13. STATE
10	I		Lea New Me
	ck Appropriate Box To Indico	ite Nature of Notice, Repor	그는 가슴을 걸 가슴을 했다.
NOTICE OF	F INTENTION TO:		SUBSEQUENT ABPORT OF I
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMEN SHOOTING OR ACIDIZ	
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(NOTE : Report	results of multiple completion on Well Recompletion Report and Log form.)
<ol> <li>Loaded hole v</li> <li>Shot off 7" oil</li> <li>Spotted cemes</li> </ol>	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1	covered 40 joints - 300 feet across stul	b of 7" casing.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing.
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regular</li> </ol>	with 11.5 pound 60 vi l string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker.	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ol> <li>Loaded hole v</li> <li>Shot off 7" oil</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regul</li> <li>Cleaned locat</li> </ol>	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme lation marker. tion, filled burn pit,	scosity mud. covered 40 joints - 300 feet across stul t across 13-3/8" so nt plug in top of 13-	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection
<ul> <li>2. Loaded hole v</li> <li>3. Shot off 7" off</li> <li>4. Spotted cemes</li> <li>5. Spotted cemes</li> <li>6. Spotted 50 for</li> <li>7. Erected regult</li> <li>8. Cleaned locat</li> </ul> 18. I hereby certify this tile fore SIGNED (This space for Federal or State)	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme: lation marker. tion, filled burn pit, tion, filled burn pit,	scosity mud. covered 40 joints - 300 feet across stul it across 13-3/8" su nt plug in top of 13- graded area around	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection well and the first state of the first state
<ol> <li>Loaded hole v</li> <li>Shot off 7" oil</li> <li>Spotted ceme:</li> <li>Spotted ceme:</li> <li>Spotted 50 for</li> <li>Erected regul</li> <li>Cleaned locat</li> </ol> 18. I hereby certify that the form SIGNED	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme: lation marker. tion, filled burn pit, tion, filled burn pit, tion, filled burn pit, TITLE ate office use)	scosity mud. covered 40 joints - 300 feet across stul it across 13-3/8" su nt plug in top of 13- graded area around	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection well is the state of
<ol> <li>Loaded hole v.</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regula</li> <li>Cleaned locat</li> </ol> 18. I hereby certer that the formation of the space for Federal or Statement of the statement of the space for Federal or Statem	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme: lation marker. tion, filled burn pit, tion, filled burn pit, tion, filled burn pit, TITLE. ate office use) TITLE.	scosity mud. covered 40 joints - 300 feet across stul it across 13-3/8" su nt plug in top of 13- graded area around Operator	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection of a state of a sta
<ol> <li>Loaded hole v.</li> <li>Shot off 7" off</li> <li>Spotted cemer</li> <li>Spotted cemer</li> <li>Spotted 50 for</li> <li>Erected regula</li> <li>Cleaned locat</li> </ol> 18. I hereby certer that the formation of the space for Federal or Statement of the statement of the space for Federal or Statem	with 11.5 pound 60 vi 1 string at 1200', Re nt plug 1100 feet to 1 nt plug 250 to 375 fee ot (0 to 50 feet) ceme: lation marker. tion, filled burn pit, tion, filled burn pit, tion, filled burn pit, TITLE. ate office use) TITLE.	scosity mud. covered 40 joints - 300 feet across stul it across 13-3/8" su nt plug in top of 13- graded area around	total 1200 feet. b of 7" casing. urface casing shoe. -3/8" surface casing. well. Ready for inspection well and the first state of the first state

i

.