



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **063659**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
TO PEROFARATE UPPER GAS ZONE	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... **SEPT. 6**, 19**63**

Well No. **1** is located **660** ft. from **[S]** line and **660** ft. from **[E]** line of sec. **28**

28 (1/4 Sec. and Sec. No.) **T 9 S R 38 E** (Meridian)
SAWYER GAS (Field) **184** (County or Subdivision) **NEW MEXICO** (State or Territory)

The elevation of the **GROUND L** derrick floor above sea level is **3924** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perofarate Gas Zone from 4915' to 4935 '. Run straddle packer and treat w/ 2000 gals. 15% HCA. follow up with 8000 gals. 15% NE-PE. (LST) acid. Test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **WESTERN DRILLING COMPANY**

Address **BOX 1392**

LONGVIEW, TEXAS

By **J. D. HENDERSON**
J. D. Henderson
Title **PARTNER**