

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-1506
7. Unit Agreement Name
8. Farm or Lease Name STATE "S"
9. Well No. 1
10. Field and Pool, or Wildcat Sawyer-San Andres Gas
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator AZTEC OIL & GAS COMPANY
3. Address of Operator P. O. Box 837, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 9-S RANGE 38-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3948 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was Plugged and Abandoned in the following manner: (12-14-72)

1. Set 100' (25 sxs cement) plug over perforations at 4872-4972'.
2. Loaded annulus with 10# mud laden fluid.
3. Set 100' (25 sxs cement) plug at Top Salt at 2300-2400'.
4. Set 100' (25 sxs cement) plug at 300-400'.
5. Set 10 sxs cement plug at Surface with Dry Hole Marker.
6. Levelled and cleared location.
7. Did not attempt to shoot casing, backed off 60'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED original signed by
LESTER L DUKE TITLE District Superintendent DATE 12-15-72

APPROVED BY John W. Runyan TITLE 12-15-72 DATE DEC 15 1973

CONDITIONS OF APPROVAL, IF ANY: