

REGISTRATION	
CERTIFICATE	
LAND OFFICE	

NEW 11002 (C-101) 11-80

Form C-103  
Supersedes Old  
C-103 and C-103  
11-80

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		6a. Indicate Type of Lease <input checked="" type="checkbox"/> Oil <input type="checkbox"/> Gas <input type="checkbox"/> Other
		6b. Oil & Gas Lease No. <b>L-4067</b>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Ike Lovelady, Inc.</b>		8. Farm or Lease Name <b>Lawton State</b>
3. Address of Operator <b>P.O. Drawer 2666; Midland, Texas 79702</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>M</b> <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>west</b> LINE, SECTION <b>32</b> TOWNSHIP <b>11-S</b> RANGE <b>38-E</b> N.M.P.M.		10. Field and Pool, or Wildcat <b>Gladila Wolfcamp</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3877 G.R.</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> <b>Complete Reentry Operation</b> <input checked="" type="checkbox"/>

17. I describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-7-80 Swabbed back load wtr. W/Trace oil, Tbg. swabbed dry. Release packer. POH. RIH W/4-3/4" bit drilled out Cmt. Ret. @ 9490', clean out ot orig. T.D. @ 12,022'.POH W/bit. RIH W/Tbg. & packer. Set packer, started swabbing to test Devonian open hole&perfs.Swabbing Approx. 140 B.W. & 5 B.O. Per day. from 2-24-80 to 2-26-80. Rig down WSU, closed well in. Flowed well to test tank every 4 to 8 days would recover approx. 10 to 20 B.O. each time well was flowed, 4-16-80 move in WSU. Release packer. POH W/Tbg. Rig up Howco, plug back from 11,022' back to 11,965'. RIH W/Packer, started swabbing. Swabbed Approx 90 B.W. & 2 B.O. per day from 4-30-80 to 5/3/80, Release packer POH W/2-3/8" Tbg. Lay down part of Tbg. string. RIH W/Tbg. for pumping. Set Tbg @ 2000'. Rig down WSU, 5-13-80. Move in WSU. Swabbed 27 B.W. & 3 B.O. 1st day.POH W/Tbg. RIH W/Tbg. & Packer set packer inside 5-1/2" Csg. @ 4246', started swabbing. Swabbed 3 B.O. & 9 B.W. Ran pump & Rods. Move off W.S.U. Waiting on pumping unit, 5-28-80 Started unit pumping. Well pumping from 5-28-80 to present, pumping into test tank approx. 20 B.W. per day W/Trace oil.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul J. Lums TITLE Manager of Drilling & Production DATE July 15, 1980

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: