

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
New Mexico "B"	
9. Well No.	
4	
10. Field and Pool, or Wildcat	
Mescelero Devonian	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Mobil Oil Corporation
3. Address of Operator
Box 633, Midland, Texas 79701
4. Location of Well
UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>10-S</u> RANGE <u>32-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
4339 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Drill Deeper in Same Zone</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Procedure to drill deeper in same zone
MIRU DD unit and POH with production equipment.
Run 4-3/4" bit, drill collars and work tubing. Drill new hole 9564' to 9660'. Dry drill if circulation is not obtained.
Run open hole logs.
Run 4" 10.46#/ft J-55 FJ liner and cement on bottom with Class H cement. Do not reverse out any cement.
Test top of liner and squeeze if necessary. Drill out to PBTD.
Perf Devonian zone as directed by geologist.
Run tubing and packer and swab test. If necessary squeeze liner and retreat.
Complete as a single Devonian producer.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 5-1-74

APPROVED BY Joe D. [Signature] TITLE Dist. [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: [Signature]