

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-66

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <u>MWJ PRODUCING COMPANY</u>		5. State Oil & Gas Lease No. <u>K-4596</u>
3. Address of Operator <u>413 First National Bank Building, Midland, Texas 79701</u>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>10South</u> RANGE <u>32 East</u> NMPM.		8. Form or Lease Name <u>Cirgo State</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4364 KB</u>		9. Well No. <u>1</u>
		10. Field and Pool, or Wildcat <u>Undesignated</u>
		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to temporarily abandon by placing bridge plug at approximately 8810' (above perforations from 8837 to 8847) and leave wellhead equipment in place to close well in at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Edward H. Judson</u> Edward H. Judson	TITLE <u>Vice-President</u>	DATE <u>April 1, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT I</u>	DATE <u>APR 5 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		